

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0001	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0001	1st	COM SPC	Lobby	Ensure TV provides closed caption during business hours.	\$36.303(e)	Implement a policy to have the closed caption feature on during business hours.
ACS	0002	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0002	1st	COM SPC	Men's Restroom	Permanent room identifying signage is mounted on the hinge side of the door.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0003	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Men's Restroom	Door has a non-compliant opening force.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0009	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0003	1st	COM SPC	Computer Room	Computers do not appear to have accessible software	\$508	Title II of the ADA requires that programs, services and activities offered by public agencies be accessible to persons with disabilities. Section 508 of the Rehabilitation Act of 1973 provides guidelines for developing, procuring, maintaining, or using electronic and information technology. Per Section 508 ensure computer provides accessible hardware/software
ACS	0013	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0006	1st	COM SPC	Women's Restroom	Permanent room identifying signage is mounted on the hinge side of the door.	\$703.4.1	Provide signage on door with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). There is no space to provide sign on latch side.
ACS	0027	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		Grade	COM SPC	Accessible Path to Entrance from Accessible parking	Curb ramp has a 11.4 % slope on the flare side.	\$406.3	Rework curb ramp to provide a 10% max. slope on the flare sides (For curb ramps with a 36" (915 mm) top landing (2010 ADA Fig. 406.3).
ACS	0030	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0010	Grade	COM SPC	Accessible Route from Public Rights of Way	Accessible route has a non-compliant cross slope of 9 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0031	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		Grade	COM SPC	Accessible Route from Public Rights of Way	Gate does not provide maneuvering clearance on pull side.	\$404.2.4	Rework slab in front of door to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	*0022	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0007	Grade	COM SPC	Accessible Parking Spaces	Left accessible parking space has 3.0 % non-compliant cross slopes.	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0023	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		Grade	COM SPC	Accessible Parking Spaces	Access aisle has 4.0 % non-compliant cross slopes.	\$502.4	Rework or repave to provide an access aisle with surface slope not exceeding 2% in all directions.
ACS	*0024	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		Grade	COM SPC	Accessible Parking Spaces	Right accessible parking space has a 2.8 % non-compliant running slope.	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0028	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		Grade	COM SPC	Accessible Path to Entrance from Accessible parking	Accessible route has a non-compliant cross slope of 3.5 % that extends 50 ft (m).	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	*0029	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0009	Grade	COM SPC	Passenger Loading Zone	Passenger loading zone has up to a 3.1 % non-compliant surface slope.	\$503.4	Restripe to provide a 60" (1524 mm) min. wide access aisle serving a 20 ft. (6096 mm) min. long vehicle pull up space with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 503.3).
ACS	0004	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Men's Restroom	Water closet side wall grab bar is mounted at 50.5" (1283 mm) perpendicular from rear wall to centerline of its outer flange.	\$604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. (2010 ADA Fig. 604.5.1)
ACS	0005	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Men's Restroom	Water closet is centered at 21.75" (552 mm) from side wall.	\$604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0006	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Men's Restroom	Toilet seat cover dispenser is mounted beyond reach ranges at 54" (1372 mm) above the finished floor and is mounted behind the water closet.	\$308.2.1	Relocate toilet seat cover dispenser and mount between 13" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). If mounted below the side wall grab bar there

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0007	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Men's Restroom	Toilet tissue dispenser is mounted over the side wall grab bar.	§609.3	Relocate toilet tissue dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3). Per 2010 ADA section 35.15(c) Safe Harbor, elements in compliance with the specifications in the 1991 Standards are not required to be retrofitted to reflect changes in the 2010 Standards.
ACS	0008	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Men's Restroom	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 52" (1321 mm) above the finished floor to highest operable part.	§308.2.1	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 52" (1321 mm) above the finished floor to highest operable part. Per 2010 ADA section 35.15(c) Safe Harbor, elements in compliance with the specifications in the 1991 Standards.
ACS	0010	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0003	1st	COM SPC	Workout Room	Exercise machines and equipment have a non-compliant clear floor space.	§1004.1	Relocate exercise machines and equipment to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space, positioned for transfer or use by an individual seated in a wheelchair (2010 ADA Fig. 305.3, 305.5).
ACS	0011	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0004	1st	COM SPC	Corridor next to Ceramics Room	Shelf protrudes into walkway, projecting 4.75" (121 mm) from back wall.	§307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge or place cane detectable object underneath (2010 ADA Fig. 307.2).
ACS	0012	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0005	1st	COM SPC	Corridor in front of Ceramics Room	Shelf protrudes into walkway, projecting 10.25" (260 mm) from back wall, and is mounted at 55" (1397 mm) above the finished floor to its bottom leading edge.	§307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0014	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Women's Restroom	Door swings into toilet compartment clear floor space.	§604.8.1.2	Reverse door swing to provide a 60" by 59" (1524 mm by 1498 mm) min. accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1).
ACS	0015	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Women's Restroom	Water closet side wall grab bar is mounted at 49" (1245 mm) perpendicular from rear wall to centerline of its outer flange.	§604.5.1	Water closet side wall grab bar is mounted at 49" (1245 mm) perpendicular from rear wall to centerline of its outer flange. Install a 34" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33" - 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface.
ACS	0016	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Women's Restroom	Water closet has the rear wall grab bar mounted at 9" (229 mm) perpendicular from side wall to centerline of inner flange.	§604.5.2	Install a 36" (914 mm) min. long rear wall grab bar that extends 24" (610 mm) min. from water closet centerline to the outer flange (on open side) of the grab bar and 12" (305 mm) min. from the water closet centerline to the inner flange (on wall side) of grab bar, mount between 33" and 36" (838 mm - 914 mm) above the floor to top of the gripping surface (2010 ADA Fig. 604.5.1).
ACS	0017	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Women's Restroom	Water closet is centered at 18.25" (464 mm) from side wall.	§604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2). For a facility that pre-dates the enactment of the ADA this dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 308.2.1.
ACS	0018	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Women's Restroom	Toilet seat cover dispenser is mounted beyond reach ranges at 54" (1372 mm) above the finished floor and is mounted behind the water closet.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3).
ACS	0019	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Women's Restroom	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 53" (1346 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object.
ACS	0020	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Women's Restroom	Lavatory is mounted at 34.25" (870 mm) above the finished floor to top of rim.	§606.3	Relocate lavatory at 34" (863 mm) max. above the finished floor to front end of rim or counter. For a facility that pre-dates the enactment of the ADA this dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.
ACS	0021	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		1st	COM SPC	Women's Restroom	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 56" (1422 mm) above the finished floor to highest operable part.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to highest operable part (2010 ADA Fig. 308.3.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0025	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312	0008	Grade	COM SPC	Accessible Path to Entrance	Bench does not provide the required clear floor space	§903.2	We recommend reworking area or relocating bench to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space positioned at the end of the bench seat parallel to the short axis of the bench.
ACS	0026	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		Grade	COM SPC	Accessible Path to Entrance	Bench does not have armrests or supportive backrest design.	§903.2	We recommend Providing a bench with a back support that is 42" (1065 mm) min. long, that extends from a point 2" (51 mm) max. above the seat surface to a point 18" (455 mm) min. above the seat surface (2010 ADA Fig. 903.4)
ACS	0032	Senior Services	Auburn Neighborhood Senior Center	300 Edgewood Ave Atlanta, GA 30312		Grade	COM SPC	Accessible Route from Public Rights of Way	Curb ramp has a 12.2 % non-compliant running slope.	§406	Rework curb ramp to provide a running slope not to exceed 8.33%
ACS	0005	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0003	Grade	COM SPC	Accessible Route From Parking to Main Entrance	Accessible route has a non-compliant cross slope of 2.5 % that extends 5 ft (1.5 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0006	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		Grade	COM SPC	Accessible Route From Parking to Main Entrance	Accessible route has a non-compliant cross slope of 2.6 % that extends 5 ft (1.5 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0007	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0004	1st	COM SPC	Passenger Loading Zone	Passenger loading zone is not striped.	§503.3	Restripe to provide a 60" (1524 mm) min. wide access aisle serving a 20 ft. (6096 mm) min. long vehicle pull up space with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 503.3).
ACS	0008	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		Grade	COM SPC	Passenger Loading Zone	Passenger loading zone does not have signage displaying the international symbol of accessibility.	§216.2	Provide a sign indicating passenger loading zone, displaying the International symbol of accessibility.
ACS	0009	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0005	1st	COM SPC	Accessible Route to bench on the Right of the Main Entrance	Planter and trash bin encroach passage width reducing it to 31" (787 mm).	§403.5.1	Relocate planter to provide a 36" (914 mm) min. clear width continuously (2010 ADA Fig. 403.5.1).
ACS	0011	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0006	1st	COM SPC	Main Entrance	Door Bell is mounted beyond required reach allowed for approach provided and is mounted at 51.5" (1308 mm) above the finished floor.	§308.2.1	Lower or install door bell at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0012	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		1st	COM SPC	Main Entrance	Key pad is mounted beyond required reach allowed for approach provided and is mounted at 51.5" (1308 mm) above the finished floor.	§308.2.1	Lower or install key pad at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0014	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0008	1st	COM SPC	Office	Permanent room identifying signage is mounted at 60.5" (1537 mm) to the baseline of the highest tactile character.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Relocate table to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area (2010 ADA Fig. 404.2.4.1).
ACS	0016	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0010	1st	COM SPC	Recreation Room 1	Table encroaches over maneuvering clearance on the pull side of the door.	§404.2.4	Relocate table to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area (2010 ADA Fig. 404.2.4.1).

Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0020	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		1st	COM SPC	Activity Room 2	Cabinet encroaches over maneuvering clearance on the pull side of the door reducing it to 11.75" (298 mm)	\$404.2.4	Relocate cabinet to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0022	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		1st	COM SPC	Activity Room 2	Doorway glazing panel is at 56" (1422 mm).	\$404.2.11	Install new door with at least one see-thru glazed panel mounted at 43" (1090 mm) max. above the finished floor.
ACS	0023	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0012	1st	COM SPC	Activity Room 1	Doorway glazing panel is at 55.75" (1416 mm).	\$404.2.11	Install new door with at least one see-thru glazed panel mounted at 43" (1090 mm) max. above the finished floor.
ACS	0024	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		1st	COM SPC	Activity Room 1	The computers at Activity Room No.1 do not appear to provide accessible software	\$508	Title II of the ADA requires that programs, services and activities offered by public agencies be accessible to persons with disabilities. Section 508 of the Rehabilitation Act of 1973 provides guidelines for developing, procuring, maintaining, or using electronic and information technology. Per Section 508 ensure computer provides accessible hardware/software
ACS	0027	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Trash bin encroaches into room signage clear floor space.	\$703.4.2	Relocate trash bin to ensure that a clear floor space of 18" (455 mm) min. by 18" (455 mm) min. centered on the tactile characters, is provided beyond the arc of the door swing, between the closed position and 45° open position (2010 ADA Fig.703.4.2).
ACS	0028	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Door has a non-compliant opening force of 10 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0040	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Door has a non-compliant opening force of 8 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	*0001	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0001	Grade	COM SPC	Two Accessible Parking Spaces on Left Side of Main Entrance (Back Row)	First accessible parking space on the right side has up to a 3.3 % non-compliant cross slope.	\$502.4	Rework or repave to provide an accessible parking space with cross slope not exceeding 2% in all directions.
ACS	*0002	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0002	Grade	COM SPC	Two Accessible Parking Spaces on Left Side of Main Entrance (Front Row)	Accessible parking space on the left side has a up to a 2.6 % non-compliant running slope.	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0003	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		Grade	COM SPC	Two Accessible Parking Spaces on Left Side of Main Entrance (Front Row)	Access aisle has a 2.8 % non-compliant cross slope.	\$502.4	Rework or repave to provide an access aisle with cross slope not exceeding 2% in all directions.
ACS	*0004	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		Grade	COM SPC	Two Accessible Parking Spaces on Left Side of Main Entrance (Front Row)	Accessible parking space on right side has a 2.7 % non-compliant cross slope.	\$502.4	Rework or repave to provide an accessible parking space with cross slope not exceeding 2% in all directions.
ACS	0010	Senior Services	Camp Tritt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0006	1st	COM SPC	Bench on the right of Main Entrance	Bench is mounted at 15.75" (400 mm) above the finished floor.	\$903.5	Rework bench to provide 17-19" (431mm-485 mm) above the finished floor seat height with armrests and supportive backrest design (for ease in sitting/standing) (2010 ADA Fig.903.4).

Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0013	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0007	1st	COM SPC	Main Lobby	Reception desk's writing surface is mounted at 34.5" (876 mm) above the finished floor to the top.	§902.3	Rework tables to provide the top of the work surface, mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. A clipboard is provided as an alternative writing surface.
ACS	0015	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0009	1st	COM SPC	Waiting Area in Lobby	Furniture encroaches passage width.	§403.5.1	Relocate furniture to provide a 36" (914 mm) min. clear width continuously (2010 ADA Fig. 403.5.1).
ACS	0017	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		1st	COM SPC		Light switch is mounted at 49.5" (1257 mm) above the finished floor to the centerline	§308.2.1	Lower or install light switch at 48" (1219 mm) maximum above the finished floor to the centerline of the highest operable part (2010 ADA Figs. 308.2.1, 308.2.2, 308.3.1). Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply.
ACS	0018	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0011	1st	COM SPC	Activity Room 2	Sink has unwrapped bottom pipes.	§804.4	Cover (insulate) sink bottom supply and drain pipes.
ACS	0019	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		1st	COM SPC	Activity Room 2	TV protrudes into walkway, projecting more than 4" (102 mm) from back wall, and is mounted at 72.5" (1842 mm) above the finished floor to its bottom leading edge.	§307.2r	Mount TV at 80" (mm) min. above the finished floor to the bottom leading edge or place a cane detectable element underneath (such as a planter) (2010 ADA Fig. 307.2).
ACS	0021	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337		1st	COM SPC	Activity Room 2	Light switch is mounted at 50" (1270 mm) above the finished floor to the centerline	§308.2.1	Lower or install light switch at 48" (1219 mm) maximum above the finished floor to the centerline of the highest operable part (2010 ADA Figs. 308.2.1, 308.2.2, 308.3.1). Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0025	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0013	1st	COM SPC	Brochure Rack in Dining Area	Brochure rack is mounted at 66.75" (1695 mm) above the finished floor to highest shelf.	§308.2.1	Lower or install brochure rack at 48" (1219 mm) max. above the finished floor to highest shelf (2010 ADA Fig. 308.2.1).
ACS	0026	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0014	1st	COM SPC	Dining Area	Condiment dispensers are mounted at 26.5" (673 mm) from edge of table.	§308.2.1	Relocate dispenser near the front edge of the table (2010 ADA Fig. 308.2.1).
ACS	0029	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Lavatory is mounted at 34.25" (870 mm) above the finished floor to top of rim.	§606.3	Relocate lavatory at 34" (863 mm) max. above the finished floor to front end of rim or counter.
ACS	0030	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Urinal is mounted in a 30.75" (781 mm) wide and 24.25" (616 mm) deep alcove.	§305.7.1	Rework partitions to provide a 36" (914 mm) min. wide alcove for a forward approach to object (2010 ADA Fig. 305.7.1).
ACS	0031	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 54" (1372 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1). Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0032	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Chair encroaches over hand dryer clear floor space.	§305.3	Relocate chair to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space at hand dryer (2010 ADA Figs. 305.3-305.5).
ACS	0033	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Hand dryer is mounted at 52" (1321 mm) above the finished floor to the highest operable part.	§308.2.1	Install hand dryer at 48" (1219 mm) max. above the finished floor to the highest operable part for a forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0034	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Accessible toilet stall door is 4.5" (114 mm) away from side wall.	§604.8.1.2	Rework partitions to provide 4" (102 mm) maximum width from side wall to stall door (2010 ADA Fig. 604.8.1.2).
ACS	0035	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Accessible stall door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0036	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 53" (1346 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object.
ACS	0037	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Toilet seat cover dispenser is mounted 1" (25 mm) under the rear wall grab bar.	§609.3	Relocate toilet seat cover to provide a clear space between the rear wall grab bar and projecting objects under of 1.5" (38 mm) min. (2010 ADA Fig. 609.3).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0038	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Toilet tissue dispenser is mounted at 1" (25 mm) in front of the water closet to the centerline of the dispenser.	§604.7	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet.
ACS	0039	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0015	1st	COM SPC	Men's Restroom Adjacent to Reception Counter	Accessible toilet compartment stall is 59.25" (1505 mm) wide.	§604.8.1.1	Relocate or rework stall partitions and/or fixtures to provide a 60" (1524 mm) wide by 59"(1498 mm) min. deep accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1).
ACS	0041	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 58" (1473 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to the highest operable part for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0042	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Chair encroaches over hand dryer clear floor space.	§305.3	Relocate chair to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space at hand dryer (2010 ADA Figs. 305.3-305.5).
ACS	0043	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Hand dryer is mounted at 52.5" (1334 mm) above the finished floor to the highest operable part.	§308.2.1	Install hand dryer at 48" (1219 mm) max. above the finished floor to the highest operable part for a forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0044	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Accessible compartment stall door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0045	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Accessible compartment stall door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0046	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Water closet side wall grab bar is mounted at 17" (432 mm) perpendicular from rear wall to centerline of its inner flange.	§604.5.1	Relocate side wall grab bar at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange and mount at 33"-36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.1)
ACS	0047	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Toilet seat cover dispenser is mounted 1" (25 mm) under the rear wall grab bar.	§609.3	Relocate toilet seat cover dispenser to provide a clear space between the rear wall grab bar and projecting objects under of 1.5" (38 mm) min. (2010 ADA Fig. 609.3).
ACS	0048	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Toilet tissue dispenser is mounted at 1" (25 mm) in front of the water closet to the centerline of the dispenser.	§604.7	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet.
ACS	0049	Senior Services	Camp Truitt Neighborhood Senior Center	4320 Herschel Road College Park, GA 30337	0016	1st	COM SPC	Women's Restroom Adjacent to Reception Counter	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 53.75" (1365 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object.
ACS	0051	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0009	1st	COM SPC	Fire Exit by Sewing Room	Emergency exit sign signage does not have Braille or raised characters and is mounted on the ceiling.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0001	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0001	1st	COM SPC	Main Entrance	Mat is not securely attached to the floor.	§302.2	Provide a securely attached mat with a leveled loop or level cut pile, with texture height that is 0.5" (13 mm) max. and has a firm cushion pad or backing (2010 ADA Fig. 302.2).
ACS	0010	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0004	1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Permanent room identifying signage does not have Braille or raised characters and is mounted on the door leaf.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0011	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Door has a non-compliant opening force of 7 lbf.	§404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0012	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Furniture encroaches over maneuvering clearance on the push side of the door.	§404.2.4	Relocate furniture to provide the required 12" (304 mm) min. maneuvering clearance on the push side of the door handle side (2010 ADA Fig. 404.2.4.1).
ACS	0013	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Trash bin encroaches over maneuvering clearance on the pull side of the door.	§404.2.4	Relocate trash bin to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0027	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0005	1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Permanent room identifying signage does not have Braille or raised characters and is mounted on the door leaf.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0042	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0007	1st	COM SPC	Computer Room	Permanent room identifying signage does not have Braille or raised characters and is mounted on the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0043	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Computer Room	Door has a non-compliant opening force of 10 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0044	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Computer Room	Computers do not appear to have accessible software.	\$508	Title II of the ADA requires that programs, services and activities offered by public agencies be accessible to persons with disabilities. Section 508 of the Rehabilitation Act of 1973 provides guidelines for developing, procuring, maintaining, or using electronic and information technology. Per Section 508 ensure computer provides accessible hardware/software
ACS	0045	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Computer Room	Furniture and trash bin encroach over maneuvering clearance on the pull side of the door reducing it to 13" (330 mm)	\$404.2.4	Relocate furniture and trash bin to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0046	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0008	1st	COM SPC	Sewing Room	Trash bin encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate trash bin and copier to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area (2010 ADA Fig. 404.2.4.1).
ACS	0052	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0010	1st	COM SPC	Women's Restroom by Ceramics Room	Door has a non-compliant opening force of 12 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0067	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ceramics Room	Trash bin encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate trash bin to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0068	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0012	1st	COM SPC	Men's Restroom by Ceramics Room	Door has a non-compliant opening force of 15 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0082	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0013	1st	COM SPC	Three Accessible Parking Spaces on Left Side of Main Entrance	First accessible parking space (from left to right) has a non-compliant running slope of up to 3.7%	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	0084	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Three Accessible Parking Spaces on Left Side of Main Entrance	The transition from the first access aisle to the sidewalk has an opening that is 1" (25 mm) wide.	\$302.3	Rework area to provide a 0.5" (12 mm) max. wide opening perpendicular to the dominant direction of travel (2010 ADA Fig.302.3).
ACS	0085	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Three Accessible Parking Spaces on Left Side of Main Entrance	The transition from the second access aisle to the sidewalk has an opening that is 1" (25 mm) wide.	\$302.3	Rework area to provide a 0.5" (12 mm) max. wide opening perpendicular to the dominant direction of travel (2010 ADA Fig.302.3).
ACS	0087	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0015	1st	COM SPC	Accessible Route From Accessible Parking Spaces Leading to Main Entrance	Accessible route has a 1.25" (32 mm) vertical change in level.	\$403.4	Rework accessible route to provide a 0.25"-0.5" (6 mm-12 mm) max. change of level, beveled with a slope no greater than 1:2 or mitigate condition by means of a curb ramp or ramp (2010 ADA Fig. 303.3).
ACS	0088	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Accessible Route From Accessible Parking Spaces Leading to Main Entrance	Accessible route has a 0.75" (19 mm) vertical change in level.	\$403.4	Rework accessible route to provide a 0.25"-0.5" (6 mm-12 mm) max. change of level, beveled with a slope no greater than 1:2 (2010 ADA Fig. 303.3).
ACS	0091	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Accessible Route From Accessible Parking Spaces Leading to Main Entrance	Bench and ash tray encroach passage width reducing it to 29" (737 mm).	\$403.5.1	Relocate ash tray provide a 36" (914 mm) min. clear width continuously (2010 ADA Fig. 403.5.1).
ACS	0092	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0016	1st	COM SPC	Passenger Loading Zone by Main Entrance	Passenger loading zone does not have signage displaying the international symbol of accessibility.	\$503	Provide signage displaying the International symbol of accessibility at passenger loading zone.
ACS	0094	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Gate encroaches passage width reducing it to 28" (711 mm).	\$403.5.1	Implement a policy to maintain gate off sidewalk to provide an accessible route that provides a 36" (914 mm) min. clear width continuously (2010 ADA Fig. 403.5.1).
ACS	0096	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Maneuvering clearance on the pull side of the gate leading to Public Rights-of-Way has a 6.9% surface slope	\$404.2.4	Rework slab to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0097	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Gate does not provide the required maneuvering clearance on the pull side.	\$404.2.4	Rework area to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	*0041	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0006	1st	COM SPC	Manager's Office	Furniture encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate furniture to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	*0083	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Three Accessible Parking Spaces on Left Side of Main Entrance	First access aisle (from left to right) has a non-compliant running slope of up to 3.0%	\$502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	*0095	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0017	1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Ramp with a slope of 7.2 % runs 10ft (3.04 mm) and does not have the required handrails.	\$405.8	Rework or repave accessible route to provide a running slope not exceeding 5%, or install handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment (2010 A
ACS	0002	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0002	1st	COM SPC	Dining Area	Fixed tables have a non-compliant knee clearance with a 16.5"(419 mm) horizontal projection.	\$902.2	Replace tables to provide 5% (3) accessible tables mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0003	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Dining Area	There is a total of 42 seating spaces provided at this area. There are no accessible tables provided.	\$902.3	Replace tables to provide 5% (3) accessible tables mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0004	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Dining Area	TV provided does not have the closed caption feature turned on.	\$36.303(e)	Implement policy to have the TV set with the closed caption on during business hours.
ACS	0005	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0003	1st	COM SPC	Chess/Backgammon Table Area	Chess/Backgammon tables have a non-compliant knee clearance and non-compliant clear floor space due to pedestal base.	\$902.2	Provide chess/backgammon tables mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. With a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance, that is 30" (762 mm) min. wide and a 17" (430 mm) min. horizontal projection.
ACS	0006	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Chess/Backgammon Table Area	Clothes rod is mounted beyond required reach allowed for approach provided and is mounted at 70.25" (1784 mm) above the finished floor.	\$308.2.1	Lower or install accessible clothes rod at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0007	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Chess/Backgammon Table Area	Closet Shelf is mounted beyond required reach range for approach provided and is mounted at 72" (1829 mm) above the finished floor.	\$811.3	Lower or install accessible shelf at 48" (1219 mm) max. above the finished floor for forward or side approach (2010 ADA Fig. 308.3.1).
ACS	0008	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Chess/Backgammon Table Area	Trash bin encroaches over hand sanitizer dispenser clear floor space.	\$305.3	Relocate trash bin to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (ADAAG Figs. 305.3-305.5).
ACS	0009	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Chess/Backgammon Table Area	Hand sanitizer is mounted beyond required reach allowed for approach provided and is mounted at 54.5" (1384 mm) above the finished floor to the highest operable part	\$308.2.1	Lower or install hand sanitizer at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0014	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 52.75" (1340 mm) above the finished floor to the highest operable part.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.3.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0015	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Lavatory has partially unwrapped bottom sink pipes.	\$606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0016	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Lavatory mirror is mounted at 50.25" (1276 mm) above the finished floor to bottom edge of its reflecting surface.	\$603.3	Lower lavatory mirror to 40" (1016 mm) max. above the finished floor to bottom edge of its reflecting surface.
ACS	0017	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Maneuvering clearance on the pull side of the stall door is 14" (356 mm).	\$404.2.4	Install dual action hinges or rework stall partitions to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area (2010 ADA Fig. 404.2.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0019	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 64" (1626 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0020	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Toilet tissue dispenser is mounted on the wrong wall.	\$604.7	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet (2010 ADA Fig. 604.7). <i>If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)</i>
ACS	0022	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Water closet side wall grab bar is mounted at 36.5" (927 mm) above the finished floor to the top of the gripping surface.	\$604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33"-36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. (2010 ADA Fig. 604.5.1)
ACS	0023	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Water closet has the rear wall grab bar mounted at 11" (279 mm) perpendicular from side wall to centerline of inner flange.	\$604.5.2	Install a 36" (914 mm) min. long rear wall grab bar that extends 12" (305 mm) min. to the centerline of the inner flange and mount between 33" and 36" (838 mm - 914 mm) above the floor to the top of the gripping surface (2010 ADA Fig 604.5.2)
ACS	0024	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Water closet rear wall grab bar is mounted at 36.5" (927 mm) above the finished floor to the top of the gripping surface.	\$604.5.2	Relocate rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface.
ACS	0025	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Toilet seat cover dispenser is mounted beyond reach ranges at 58" (1473 mm) above the finished floor.	\$308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0026	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Sanitary napkin disposal container is mounted beyond required reach allowed for approach provided and is mounted at 55.5" (1410 mm) above the finished floor to the highest operable part.	\$308.2.1	Lower or install sanitary napkin disposal container at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0028	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Lavatory mirror is mounted at 50.25" (1276 mm) above the finished floor to bottom edge of its reflecting surface.	\$603.3	Lower lavatory mirror to 40" (1016 mm) max. above the finished floor to bottom edge of its reflecting surface.
ACS	0029	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 52.5" (1334 mm) above the finished floor to paper.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0030	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Secondary paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 58" (1473 mm) above the finished floor to paper.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0031	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Paper towel dispenser protrudes into walkway, projecting 11" (279 mm) from back wall, and is mounted at 52" (1321 mm) above the finished floor to its bottom leading edge.	\$307.2r	Relocate or recess paper towel dispenser so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0032	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Urinal is mounted in a 30" (762 mm) wide and 24.5" (622 mm) deep alcove.	\$305.7.1	Relocate privacy partition to provide a 36" (914 mm) min. wide alcove for a forward approach to object (2010 ADA Fig. 305.7.1).
ACS	0034	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 64.75" (1645 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0035	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Accessible toilet compartment (stall) is 49.75" (1264 mm) wide.	\$604.8.1.1	Relocate stall partitions to provide a 60" (1524 mm) wide by 59" (1498 mm) min. deep accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1).
ACS	0036	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Toilet tissue dispenser is mounted on the wrong wall.	\$604.7	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet (2010 ADA Fig. 604.7). <i>If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)</i>

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0037	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Toilet seat cover dispenser is mounted beyond reach ranges at 58" (1473 mm) above the finished floor to the slot.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0038	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Water closet flush control is toward the wall side.	§604.6	Rotate water closet flush control toward the open side or install an electronically controlled mechanism.
ACS	0039	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Water closet side wall grab bar is mounted at 36.25" (921 mm) above the finished floor to the top of the gripping surface.	§604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.1). For a facility that pre-dates the enactment of the ADA this dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.
ACS	0040	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Water closet rear wall grab bar is mounted at 36.25" (921 mm) above the finished floor to the top of the gripping surface.	§604.5.2	Relocate rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. For a facility that pre-dates the enactment of the ADA this dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.
ACS	0047	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Sewing Room	Trash bin encroaches over hand sanitizer clear floor space.	§305.3	Relocate trash bin to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (ADAAG Figs. 305.3-305.5).
ACS	0048	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Sewing Room	Emergency exit sign signage does not have Braille or raised characters and is mounted on the ceiling.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0049	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Sewing Room	Hand sanitizer is mounted beyond required reach allowed for approach provided and is mounted at 50.75" (1289 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install hand sanitizer at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0050	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Sewing Room	Accessible route leading to exercise equipment has a non-compliant clear width.	§403.5.1	Relocate exercise equipment to provide a 36" (914 mm) min. clear width continuously (2010 ADA Fig. 403.5.1).
ACS	0053	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 57" (1448 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.3.1).
ACS	0054	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Lavatory has partially unwrapped bottom sink pipes.	§606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0055	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Shelf is mounted beyond required reach allowed for approach provided and is mounted at 36.25" (921 mm) above the finished floor.	§603.4	Relocate shelf to another location and mount between 40"- 48" (1016 mm - 1219 mm) max. above the finished floor for forward approach to object
ACS	0058	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Maneuvering clearance on the pull side of the stall door is 5.25" (133 mm).	§404.2.4	Rework stall partitions to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area (2010 ADA Fig. 404.2.4.1).
ACS	0059	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 55" (1397 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object.
ACS	0060	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Toilet seat cover dispenser is mounted beyond reach ranges at 50.5" (1283 mm) above the finished floor.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor, Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0061	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Water closet has the rear wall grab bar mounted at 10" (254 mm) perpendicular from side wall to centerline of inner flange.	§604.5.2	Install a 36" (914 mm) min. long rear wall grab bar that extends 12" (305 mm) min. to the centerline of the inner flange and mount between 33" and 36" (838 mm - 914 mm) above the floor to the top of the gripping surface (2010 ADA Fig 604.5.2)

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0062	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Water closet side wall grab bar is mounted at 12.5" (318 mm) perpendicular from rear wall to centerline of its inner flange.	§604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. (2010 ADA Fig. 604.5.1)
ACS	0063	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Toilet tissue dispenser is mounted at 2" (51 mm) in front of the water closet to the centerline of the dispenser.	§604.7	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet (2010 ADA Fig. 604.7). If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)
ACS	0064	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Shelf is mounted 4.25" (108 mm) over the side wall grab bar.	§609.3	Relocate shelf to another location and mount between 40"- 48" (1016 mm -1219 mm) max. above the finished floor for forward approach to object
ACS	0065	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Shelf is mounted beyond required reach allowed for approach provided and is mounted at 39.25" (997 mm) above the finished floor.	§603.4	Lower or install shelf between 40"- 48" (1016 mm -1219 mm) max. above the finished floor for forward approach to object.
ACS	0066	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0011	1st	COM SPC	Ceramics Room	Sink has unwrapped bottom pipes.	§804.4	Cover (insulate) sink bottom supply and drain pipes.
ACS	0069	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 59" (1499 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.3.1).
ACS	0070	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Paper towel dispenser protrudes into walkway, projecting 11" (279 mm) from back wall, and is mounted at 53.25" (1353 mm) above the finished floor to its bottom leading edge.	§307.2	Relocate or recess paper towel dispenser so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0071	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Lavatory has partially unwrapped bottom sink pipes.	§606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0072	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Lavatory mirror is mounted at 40.5" (1029 mm) above the finished floor to bottom edge of its reflecting surface.	§603.3	Lower lavatory mirror to 40" (1016 mm) max. above the finished floor to bottom edge of its reflecting surface.
ACS	0075	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 56" (1422 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object.
ACS	0076	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Toilet tissue dispenser is mounted on the wrong wall.	§604.7	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet (2010 ADA Fig. 604.7). If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)
ACS	0077	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Toilet seat cover dispenser is mounted beyond reach ranges at 51.25" (1302 mm) above the finished floor to the slot.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor to the slot for unobstructed forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0078	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 55.75" (1416 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object.
ACS	0079	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Water closet side wall grab bar is mounted at 12.5" (318 mm) perpendicular from rear wall to centerline of its inner flange.	§604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. (2010 ADA Fig. 604.5.1)
ACS	0080	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Shelf is mounted 4" (102 mm) over the side wall grab bar.	§609.3	Relocate shelf to another location and mount between 40"- 48" (1016 mm -1219 mm) max. above the finished floor for forward approach to object
ACS	0081	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Shelf is mounted beyond required reach allowed for approach provided and is mounted at 39" (991 mm) above the finished floor.	§603.4	Relocate shelf to another location and mount between 40"- 48" (1016 mm -1219 mm) max. above the finished floor for forward approach to object

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0086	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318	0014	1st	COM SPC	Outdoor Seating Area in Front of Accessible Parking Spaces	Tables have a non-compliant knee clearance with a 10" (254 mm) horizontal projection.	§902.2	Replace tables to provide 5% (1) accessible tables mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b)).
ACS	0089	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Accessible Route From Accessible Parking Spaces Leading to Main Entrance	Benches are mounted at 16" (406 mm) above the finished floor.	§903.5	We recommend as best practice providing benches with seat mounted at 17-19" (431mm-485 mm) above the finished floor with armrests and supportive backrest design (for ease in sitting/standing) (2010 ADA Fig.903.4).
ACS	0090	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Accessible Route From Accessible Parking Spaces Leading to Main Entrance	Bench back support is mounted at 17.5" (444 mm) above the seat surface	§903.4	We recommend as best practice providing bench with a back support that is 42" (1065 mm) min. long, that extends from a point 2" (51 mm) max. above the seat surface to a point 18" (455 mm) min. above the seat surface (2010 ADA Fig. 903.4)
ACS	0093	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Passenger Loading Zone by Main Entrance	Passenger loading zone access aisle needs to be striped.	§503.3.1	Restripe area to provide a 60" (1524 mm) min. wide access aisle serving a 20 ft. (6096 mm) min. long vehicle pull up space with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 503.3).
ACS	*0021	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Accessible toilet compartment (stall) is 52.25" (1327 mm) wide.	§604.8.1.1	Relocate or rework stall partitions and/or fixtures to provide a 60" (1524 mm) wide by 59" (1498 mm) min. deep accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1).
ACS	0018	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Ladies Restroom by Chess/Backgammon Table Area	Toilet compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.1.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0033	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Chess/Backgammon Table Area	Toilet compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.1.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0056	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Toilet compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.1.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0057	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Women's Restroom by Ceramics Room	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0073	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0074	Senior Services	Dogwood Neighborhood Senior Center	1953 Donald Lee Hollowell Pkwy NW Atlanta, GA 30318		1st	COM SPC	Men's Restroom by Ceramics Room	Toilet compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.1.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0012	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Women's Accessible Restroom No. 127	Door has a non-compliant opening force of 14 lbf.	§404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0018	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Sewing Room No. 125	Vision lights are mounted at 48" (1219 mm) above the finished floor.	§404.2.11	Provide at least one see-thru glazed panel mounted at 43" (1090 mm) max. above the finished floor.
ACS	0026	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Computer Room No. 125	Vision lights are mounted at 48" (1219 mm) above the finished floor.	§404.2.11	Provide at least one see-thru glazed panel mounted at 43" (1090 mm) max. above the finished floor.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0027	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Computer Room No. 125	Computers do not appear to have accessible software.	§508	Title II of the ADA requires that programs, services and activities offered by public agencies be accessible to persons with disabilities. Section 508 of the Rehabilitation Act of 1973 provides guidelines for developing, procuring, maintaining, or using electronic and information technology. Per Section 508 ensure computer provides accessible hardware/software
ACS	0029	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Fitness Room No. 122	Vision lights are mounted at 48" (1219 mm) above the finished floor.	§404.2.11	Provide at least one see-thru glazed panel mounted at 43" (1090 mm) max. above the finished floor.
ACS	0032	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Game Room No. 120	Vision lights are mounted at 48" (1219 mm) above the finished floor.	§404.2.11	Provide at least one see-thru glazed panel mounted at 43" (1090 mm) max. above the finished floor.
ACS	0037	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Lounge Room No. 116	Vision lights are mounted at 48.25" (1226 mm) above the finished floor.	§404.2.11	Provide at least one see-thru glazed panel mounted at 43" (1090 mm) max. above the finished floor.
ACS	0041	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0012	Grade	COM SPC	Four Accessible parking Spaces on Right Side of Main Entrance	Accessible parking spaces are not clearly outlined or need re-striping.	§502.3.1	Restripe to provide a van-accessible parking space 96" (2438 mm) min. wide and a 96" (2438 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (When access aisle is 96" (2438) wide) (2010 ADA Figs. 502.2).
ACS	0048	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0013	1st	COM SPC	Accessible Route From the Accessible parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.6 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0049	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From the Accessible parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.4 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0050	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From the Accessible parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.1 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0051	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From the Accessible parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 2.8 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0052	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From the Accessible parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 2.9 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0053	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From the Accessible parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 2.8 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0054	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From the Accessible parking Spaces Leading to Main Entrance	Accessible route has a non-compliant running slope of 7.8 %.	§403.3 §405.8	Rework or repave area to provide a running slope not exceeding 5%. Or install handrails mounted between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment (2010 ADA Fig. 505.4, 505.6, 505.10.1)
ACS	0055	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From the Accessible parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.0 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0056	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0014	1st	COM SPC	Passenger Loading Zone by Main Entrance	Passenger loading zone does not have signage displaying the international symbol of accessibility.	§503	Provide signage displaying the International symbol of accessibility at passenger loading zone.
ACS	0057	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0015	1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 4.6 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0058	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 6.0 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0059	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 6.3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0060	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 2.7 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0062	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Both curb ramps project into vehicular traffic lanes and do not have truncated domes	\$705	We recommend as best practice providing truncated domes with a base diameter of 0.9"-1.4" (22 mm-35 mm), a height of 0.2" (35 mm), center-to-center spacing of 1.6"-2.4" (40 mm-61 mm), and base-to-base spacing of 0.65" (17 mm) that contrast visually with adjoining surface.
ACS	0063	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route over the asphalt has a non-compliant cross slope of 4.1 % that extends 20 ft (6.08 mt).	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0064	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant vertical change in level at the transition from concrete to asphalt.	\$403.4	Rework accessible route to provide a 0.25"-0.5" (6 mm-12 mm) max. change of level, beveled with a slope no greater than 1:2 or mitigate condition by means of a curb ramp or ramp (2010 ADA Fig. 303.3).
ACS	0065	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Secondary curb ramp has a 11.7 % non-compliant running slope.	\$406	Rework curb ramp to provide a running slope not to exceed 8.33%
ACS	0066	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Curb ramp has non-compliant slopes on the flare sides.	\$406.3	Rework curb ramp to provide a 10% max. slope on the flare sides (For curb ramps with a 36" (915 mm) top landing (2010 ADA Fig. 406.3).
ACS	0067	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 4.7 % that extends 10 ft (3.04 mt).	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0068	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 6.5 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0069	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 5.2 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0070	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 3.6 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0071	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 3.4 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0072	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 3.0 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0073	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 3.5 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0074	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 5.3 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0075	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 3.4 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0076	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 4.5 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0080	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 4.8 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0081	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	There is no signage posted indicating the location of an accessible entrance.	§403.3	Post signage indicating location of the accessible entrance serving the facility. If sign is to be placed overhead it shall have a minimum character height of 3" (76 mm).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	*0042	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		Grade	COM SPC	Four Accessible parking Spaces on Right Side of Main Entrance	First accessible parking space (from left to right) has a non-compliant running slope of up to 4%	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0043	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		Grade	COM SPC	Four Accessible parking Spaces on Right Side of Main Entrance	First access aisle (from left to right) has a non-compliant running slope of up to 5.6%	\$502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	*0044	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		Grade	COM SPC	Four Accessible parking Spaces on Right Side of Main Entrance	Second accessible parking space (from left to right) has a non-compliant running slope of up to 4.7%	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0045	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		Grade	COM SPC	Four Accessible parking Spaces on Right Side of Main Entrance	Third accessible parking space (from left to right) has a non-compliant running slope of up to 5.0%	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0046	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		Grade	COM SPC	Four Accessible parking Spaces on Right Side of Main Entrance	Second access aisle (from left to right) has a non-compliant running slope of up to 4%	\$502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	*0047	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		Grade	COM SPC	Four Accessible parking Spaces on Right Side of Main Entrance	Fourth accessible parking space (from left to right) has a non-compliant running slope of up to 3.7%	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0061	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Curb ramp has a non-compliant running slope of up to 9.0%	\$406	Rework curb ramp to provide a running slope not to exceed 8.33%
ACS	*0077	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 3.7 % that extends 15 ft (4.57 mt).	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	*0078	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 2.5 % that extends 15 ft (4.57 mt).	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	*0079	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 3.0 % that extends 10 ft (3.04 mt).	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0001	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0001	1st	COM SPC	Lobby	Brochure rack is mounted at 66.75" (1695 mm) above the finished floor to highest shelf.	\$308.2.1	Lower or install brochure rack at 48" (1219 mm) max. above the finished floor to highest shelf (2010 ADA Fig. 308.2.1).
ACS	0006	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0004	1st	COM SPC	Men's Accessible Restroom No. 128	Toilet compartment (stall) door does not provide pull handles on both sides of the door near the latch.	\$604.8.1.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0007	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Men's Accessible Restroom No. 128	Accessible toilet compartment (stall) door is located more than 4" (102 mm) from the side wall or partition farthest from the water closet	\$604.8.1.2	Reconfigure accessible toilet compartment (stall) to provide a self closing door with opening mounted at 4" (101 mm) max. from the side wall or partition farthest from the water closet (For door located in front of partition) (2010 ADA Fig. 604.8.1.1)
ACS	0008	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Men's Accessible Restroom No. 128	Water closet is centered at 18.25" (464 mm) from side wall.	\$604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2). <i>This dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.</i>
ACS	0010	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Men's Accessible Restroom No. 128	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 50.5" (1283 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object.
ACS	0013	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Women's Accessible Restroom No. 127	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 50.75" (1289 mm) above the finished floor to the highest operable part.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to the highest operable part for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0015	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Women's Accessible Restroom No. 127	Accessible toilet compartment (stall) door is located more than 4" (102 mm) from the side wall or partition farthest from the water closet	\$604.8.1.2	Reconfigure accessible toilet compartment (stall) to provide a self closing door with opening mounted at 4" (101 mm) max. from the side wall or partition farthest from the water closet (For door located in front of partition) (2010 ADA Fig. 604.8.1.1)
ACS	0016	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Women's Accessible Restroom No. 127	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 52" (1321 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0019	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Sewing Room No. 125	Trash bin encroaches over thermostat clear floor space.	\$305.3	Relocate trash bin to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0020	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Sewing Room No. 125	Trash bin encroaches over maneuvering clearance on the pull side of the door.	§404.2.4	Relocate trash bin to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0021	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Sewing Room No. 125	Shelf is mounted beyond required reach range for approach provided and is mounted at 58.5" (1486 mm) above the finished floor.	§308.2.1	Lower or install accessible shelf at 48" (1219 mm) max. above the finished floor for forward (2010 ADA Fig. 308.3.1).
ACS	0022	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Sewing Room No. 125	Desk has a non-compliant 23.75" (603 mm) knee clearance.	§902.2	Provide desk with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance, that is 30" (762 mm) min. wide and has a 17" (430 mm) horizontal projection.
ACS	0023	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Sewing Room No. 125	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 60.25" (1530 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0024	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Sewing Room No. 125	Telephone is mounted at 59.5" (1511 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0030	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Fitness Room No. 122	Telephone is mounted at 60" (1524 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0033	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Game Room No. 120	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 58.25" (1480 mm) above the finished floor.	§308.3	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0034	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0009	1st	COM SPC	Cafeteria	Tray slide surface is mounted at 34.75" (883 mm) above the finished floor.	§902.3	Rework to provide the top of the tray slide surface mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground.
ACS	0035	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Cafeteria	Beverage dispensers are mounted beyond required reach allowed for approach provided and is mounted at 50.25" (1276 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install beverage dispensers at 48" (1219 mm) max. above the finished floor for floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0036	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Cafeteria	Beverage dispensers are mounted beyond required reach allowed for approach provided and is mounted at 49.75" (1214 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install beverage dispensers at 48" (1219 mm) max. above the finished floor for floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0039	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Resting Room No. 109	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 56.25" (1429 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to the highest operable part for forward approach to object (2010 ADA Fig. 308.3.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0040	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Resting Room No. 109	Wall cabinets over the work surface are mounted at 57.5" (1460 mm) above the finished floor to the bottom shelf.	\$804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	*0005	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Men's Accessible Restroom No. 128	Urinal is mounted at 17.5" (444 mm) above the finished floor to top of rim.	\$605.2	Lower urinal and mount at 17" (431 mm) max. above the finished floor to top of rim. (2010 ADA Fig. 605.2)
ACS	*0014	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Women's Accessible Restroom No. 127	Toilet compartment (stall) door does not provide pull handles on both sides of the door near the latch.	\$604.8.1.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0002	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0002	1st	COM SPC	Coat Room No. 103	Permanent room identifying signage is mounted at 63" (1600 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0003	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0002	1st	COM SPC	Men's Accessible Restroom No. 128	Permanent room identifying signage is mounted at 61.75" (1568 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0004	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Men's Accessible Restroom No. 128	Permanent room identifying signage is mounted at 62" (1575 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0009	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Men's Accessible Restroom No. 128	Toilet seat cover dispenser is mounted 5.5" (140 mm) over the side wall grab bar.	\$609.3	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). <i>If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar . If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)</i>
ACS	0011	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354		1st	COM SPC	Women's Accessible Restroom No. 127	Permanent room identifying signage is mounted at 62.25" (1581 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0017	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0005	1st	COM SPC	Sewing Room No. 125	Permanent room identifying signage is mounted at 62" (1575 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0025	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0006	1st	COM SPC	Computer Room No. 125	Permanent room identifying signage is mounted at 62.25" (1581 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0028	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0007	1st	COM SPC	Fitness Room No. 122	Permanent room identifying signage is mounted at 62.75" (1340 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0031	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0008	1st	COM SPC	Game Room No. 120	Permanent room identifying signage is mounted at 62.25" (1835 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0036	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0010	1st	COM SPC	Lounge Room No. 116	Permanent room identifying signage is mounted at 62.75" (1594 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0038	Senior Services	Hapeville Neighborhood Senior Center	527 King Arnold Street Hapeville, GA 30354	0011	1st	COM SPC	Resting Room No. 109	Permanent room identifying signage is mounted at 62.75" (1594 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0092	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0020	Grade	COM SPC	Path from the Two Accessible Parking Spaces on the Right Side to Main Entrance	There are no detectable warnings or contrasting surface provided at curb edge.	\$705.2	We recommend providing detectable warnings surfaces at curb edge that are 24" (610 mm) min. from curb edge and extend the full width of the sidewalk.
ACS	0002	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	First accessible parking space from the left needs to be restriped.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0003	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	First access aisle from left to right has a 2.8 % non-compliant cross slope.	\$502.4	Rework or repave to provide an access aisle with surface slope not exceeding 2% in all directions.
ACS	0004	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	First access aisle from left to right has a 2.4 % non-compliant running slope.	\$502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	0005	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	Access aisle needs to be restriped	\$502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).
ACS	0006	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	Second accessible parking space from left to right has a 2.7 % non-compliant surface slope.	\$502.4	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	0007	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	Second accessible parking space from left to right needs to be restriped.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0008	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	Third accessible parking space from the left needs to be restriped.	§502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0009	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	Second access aisle from left to right is not striped.	§502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).
ACS	0010	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	Fourth accessible parking space from the left needs to be restriped.	§502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0011	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0002		COM SPC	Path from Accessible Parking Spaces on the Left Side of Main entrance	Accessible route has a non-compliant cross slope of 3.3 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0012	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Path from Accessible Parking Spaces on the Left Side of Main entrance	Accessible route has a non-compliant cross slope of 4.2 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0013	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Path from Accessible Parking Spaces on the Left Side of Main entrance	Accessible route has a non-compliant cross slope of 3.6 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0014	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Path from Accessible Parking Spaces on the Left Side of Main entrance	Accessible route has a non-compliant cross slope of 3.2 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0015	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Path from Accessible Parking Spaces on the Left Side of Main entrance	Accessible route has a non-compliant cross slope of 2.9 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0016	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Path from Accessible Parking Spaces on the Left Side of Main entrance	Accessible route has a non-compliant cross slope of 4.2 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0017	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Path from Accessible Parking Spaces on the Left Side of Main entrance	Accessible route has a non-compliant cross slope of 3.1 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0018	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Path from Accessible Parking Spaces on the Left Side of Main entrance	Accessible route has a non-compliant running slope of 5.2 % that extends 10 ft (3.04 mt).	§403.3	Rework or repave accessible route to provide a running slope not exceeding 2%.
ACS	0019	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Path from Accessible Parking Spaces on the Left Side of Main entrance	Accessible route has a non-compliant cross slope of 5.3 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0020	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0003		COM SPC	Passenger Loading Zone	Passenger loading zone does not have signage displaying the international symbol of accessibility.	§216.2	Provide a sign indicating passenger loading zone, displaying the International symbol of accessibility.
ACS	0021	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213			COM SPC	Passenger Loading Zone	Passenger loading zone is not striped.	§503.4	Stripe to provide a 60" (1524 mm) min. wide access aisle serving a 20 ft. (6096 mm) min. long vehicle pull up space with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 503.3).
ACS	0022	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0004		COM SPC	Main Entrance	Curb ramp has a 10 % non-compliant running slope.	§406	Rework area measuring 86" x 20" (2184 mm x 6096) with surface slopes 2% max. Rework sidewalk and relocate curb ramp with an 8.33% max. running slope that does not project into vehicular traffic lanes adjacent to previous passenger loading zone on the south side.
ACS	0028	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0007	1st	COM SPC	Unisex Restroom 124	Characters have a non-compliant glare finish.	§703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0032	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Unisex Restroom 124	Door has a non-compliant opening force of 7 lbf.	§404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0033	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0008	1st	COM SPC	Office 131	Permanent room identifying signage is mounted at 60.5" (1537 mm) to the baseline of the highest tactile character.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0034	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Office 131	Characters have a non-compliant glare finish.	§703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0035	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0009	1st	COM SPC	Quiet Room 130	Permanent room identifying signage is mounted at 60.5" (1537 mm) to the baseline of the highest tactile character.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0036	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Quiet Room 130	Characters have a non-compliant glare finish.	\$703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0042	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0010	1st	COM SPC	Lounge 129	Permanent room identifying signage is mounted at 61" (1549 mm) to the baseline of the lowest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0043	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Lounge 129	Characters have a non-compliant glare finish.	\$703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0046	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0012	1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Permanent room identifying signage is mounted on the hinge side of the door.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0047	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Characters have a non-compliant glare finish.	\$703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0048	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Door has a non-compliant opening force of 10 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0057	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0013	1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Permanent room identifying signage is mounted on the hinge side of the door.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0058	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Characters have a non-compliant glare finish.	\$703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0068	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0014	1st	COM SPC	Game Room 115	Permanent room identifying signage is mounted at 60.5" (1537 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0069	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Game Room 115	Characters have a non-compliant glare finish.	\$703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0071	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0015	1st	COM SPC	Quilting 114	Permanent room identifying signage is mounted at 60.5" (1537 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0072	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Quilting 114	Characters have a non-compliant glare finish.	\$703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0074	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0016	1st	COM SPC	Exercise 110	Permanent room identifying signage is mounted at 60.5" (1537 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0075	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Exercise 110	Characters have a non-compliant glare finish.	\$703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0079	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0017	1st	COM SPC	Computer 109	Permanent room identifying signage is mounted at 60.5" (1537 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0080	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Computer 109	Characters have a non-compliant glare finish.	\$703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0081	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0018	1st	COM SPC	Arts and Crafts 108	Permanent room identifying signage is mounted at 60.5" (1537 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0082	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Arts and Crafts 108	Characters have a non-compliant glare finish.	\$703.5.1	Rework / replace signage to provide characters with a non-glare finish, that contrast with their field with either a light pictogram on a dark field, or a dark pictogram on a light field.
ACS	0086	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0019	Grade	COM SPC	Two Accessible Parking Spaces on the Right Side of Main Entrance	Left accessible parking space is faded.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0089	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Two Accessible Parking Spaces on the Right Side of Main Entrance	Access aisle needs to be restriped.	\$502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).
ACS	0091	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Two Accessible Parking Spaces on the Right Side of Main Entrance	Right accessible parking space needs to be restriped.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (1525 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0094	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Path from the Two Accessible Parking Spaces on the Right Side to Main Entrance	Accessible route has a non-compliant cross slope of 2.8 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0095	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Path from the Two Accessible Parking Spaces on the Right Side to Main Entrance	Accessible route has a non-compliant cross slope of 2.9 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0096	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Path from the Two Accessible Parking Spaces on the Right Side to Main Entrance	Accessible route has a non-compliant cross slope of 3.6 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0097	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Path from the Two Accessible Parking Spaces on the Right Side to Main Entrance	Accessible route has a non-compliant cross slope of 3.3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0098	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Path from the Two Accessible Parking Spaces on the Right Side to Main Entrance	Accessible route has a non-compliant cross slope of 3.1 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0099	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Path from the Two Accessible Parking Spaces on the Right Side to Main Entrance	Accessible route has a non-compliant cross slope of 2.6 %.	\$403.3	
ACS	*0001	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0001	Grade	COM SPC	Four Accessible Parking Spaces on the Left Side of Main Entrance	First accessible parking space from the left has up to a 3.1 % non-compliant running slopes.	\$502.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0087	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Two Accessible Parking Spaces on the Right Side of Main Entrance	Left accessible parking space has a 3.2 % non-compliant running slope.	\$502.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0088	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Two Accessible Parking Spaces on the Right Side of Main Entrance	Access aisle has up to a 3.9 % non-compliant running slopes.	\$502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	*0090	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Two Accessible Parking Spaces on the Right Side of Main Entrance	Right accessible parking space has up to a 3.3 % non-compliant running slope.	\$502.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0093	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		Grade	COM SPC	Path from the Two Accessible Parking Spaces on the Right Side to Main Entrance	Accessible route has a non-compliant running slope of 7.6 %.	\$403.3, \$405.8	Rework or repave accessible route to provide a running slope not exceeding 5%. Alternative is to install handrails. For ramps rising over 6" (152 mm) provide handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment.
ACS	0023	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0005	1st	COM SPC	Reception Area	Counter is mounted at 36.25" (921 mm) above the finished floor.	\$904.4.1	Provide an alternative counter or rework main counter to provide a portion that is 36" (914 mm) min. long, mounted at 36" (914 mm) max. above the finished floor to the top. <i>This dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.</i>

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0024	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Reception Area	Magazine rack is mounted beyond required reach allowed for approach provided and is mounted at 68" (1727 mm) above the finished floor.	§308.3.1	Lower or install at 48" (1219 mm) max. above the finished floor for side approach to object (2010 ADA Fig. 308.3.1).
ACS	0025	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Reception Area	Magazine rack is mounted beyond required reach allowed for approach provided and is mounted at 67.75" (1721 mm) above the finished floor.	§308.3.1	Lower or install at 48" (1219 mm) max. above the finished floor for side approach to object (2010 ADA Fig. 308.3.1).
ACS	0026	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Reception Area	Counter is mounted at 36.25" (921 mm) above the finished floor.	§904.4.1	Provide an alternative counter or rework main counter to provide a portion that is 36" (914 mm) min. long, mounted at 36" (914 mm) max. above the finished floor to the top. <i>This dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.</i>
ACS	0027	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0006	1st	COM SPC	Corridor leading to Quiet Room	AED protrudes into walkway, projecting 4.5" (114 mm) from back wall, and is mounted at 42" (1067 mm) above the finished floor to its bottom leading edge.	§307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0029	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Unisex Restroom 124	Toilet seat cover dispenser is mounted beyond reach ranges and is mounted behind the water closet.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0030	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Unisex Restroom 124	Water closet seat is mounted at 16.75" (425 mm) above the finished floor to top.	§604.4	Retrofit water closet seat and mount between 17" and 19" (431 mm - 482 mm) above the finished floor to top of seat.
ACS	0031	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Unisex Restroom 124	Lavatory is 49" (1245 mm) from side wall and encroaches water closet clear floor space.	§604.3.1	Rework partitions and/or fixtures to provide a 60" by 56" (1524 mm by 1420 mm) min. water closet clear floor space for a floor mounted water closet (2010 ADA Fig. 604.3.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991</i>
ACS	0037	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Quiet Room 130	Lavatory has unwrapped bottom sink pipes.	§606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0038	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Quiet Room 130	Chair encroaches over lavatory clear floor space.	§606.2	Relocate chair to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (ADAAG Figs. 305.3-305.5).
ACS	0039	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Quiet Room 130	Lavatory does not provide the required knee clearance.	§606.2.2	Rework lavatory to provide the required 27" (685 mm) min. knee clearance above the finished floor to bottom leading edge of fixture at an 8" (203 mm) min. horizontal projection (2010 ADA Fig. 306.3).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0040	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Quiet Room 130	Sink is mounted at 36.25" (921 mm) above the finished floor to the top.	\$606.3.2	Relocate / rework sink and mount at 34" (863 mm) max. above the finished floor to top of counter.
ACS	0041	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Quiet Room 130	Wall cabinets over the work surface are mounted at 48.75" (1238 mm) above the finished floor to the bottom shelf.	\$804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0044	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Lounge 129	Books are mounted beyond required reach allowed for approach provided and are mounted at 54" (1372 mm) above the finished floor over an obstruction.	\$308.3.1	Lower or install at 48" (1219 mm) max. above the finished floor for side approach to object without an obstruction (2010 ADA Fig. 308.3.1). Implement policy to assist customers by retrieving books from inaccessible shelves and post signage indicating that assistance is available upon request. (§36.304 (f) and §36.305 (b) (3)).
ACS	0045	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213	0011	1st	COM SPC	Corridor by Drinking Fountains on Left side of Reception Area	Hand sanitizer dispenser is mounted beyond required reach allowed for approach provided and is mounted at 51.75" (1314 mm) above the finished floor	\$308.2.1	Lower or install hand sanitizer dispenser at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0051	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Toilet seat cover dispenser is mounted beyond reach ranges and is mounted behind the water closet.	\$308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0052	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Water closet seat is mounted at 16.5" (419 mm) above the finished floor to top.	\$604.4	Retrofit water closet seat and mount between 17" and 19" (431 mm - 482 mm) above the finished floor to top of seat.
ACS	0053	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Water closet has a 30" (762 mm) long rear wall grab bar.	\$604.5.2	Install a 36" (914 mm) min. long rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.2).
ACS	0054	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Lavatory is 37.5" (952 mm) from side wall and encroaches water closet clear floor space.	\$604.3.1	Rework partitions and/or fixtures to provide a 60" by 56" (1524 mm by 1420 mm) min. water closet clear floor space for a floor mounted water closet (2010 ADA Fig. 604.3.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991
ACS	0056	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Trash can encroaches over paper towel dispenser clear floor space.	\$305.3	Relocate trash can to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (ADAAG Figs. 305.3-305.5).
ACS	0059	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Soap dispenser is mounted beyond required reach allowed for approach provided at 48.25" (1226 mm) above the finished floor over an obstruction (sink counter).	\$308.2.1	Lower or install soap dispenser at 44" (1219 mm) max. above the finished floor to the highest operable part, over a 20" - 25" (510 mm - 1120 mm) max. obstruction, and at 15" (381 mm) min. above the finished floor to the centerline for forward approach to object (2010 ADA Fig. 308.2.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0062	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Toilet seat cover dispenser is mounted beyond reach ranges and is mounted behind the water closet.	\$308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0063	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Lavatory mirror is mounted at 40.5" (1029 mm) above the finished floor to bottom edge of its reflecting surface.	\$603.3	Lower lavatory mirror to 40" (1016 mm) max. above the finished floor to bottom edge of its reflecting surface.
ACS	0064	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Water closet has a 30" (762 mm) long rear wall grab bar.	\$604.5.2	Install a 36" (914 mm) min. long rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig.604.5.2).
ACS	0065	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Lavatory is 36.75" (933 mm) from side wall and encroaches water closet clear floor space.	\$604.3.1	Rework partitions and/or fixtures to provide a 60" by 56" (1524 mm by 1420 mm) min. water closet clear floor space for a floor mounted water closet (2010 ADA Fig. 604.3.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991
ACS	0066	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Water closet seat is mounted at 16.5" (419 mm) above the finished floor to top.	\$604.4	Retrofit water closet seat and mount between 17" and 19" (431 mm - 482 mm) above the finished floor to top of seat.
ACS	0070	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Game Room 115	Tables have a non-compliant 25.5" (648 mm) knee clearance.	\$902.2	Provide seating with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance above the finished floor and a 17" (430 mm) horizontal projection.
ACS	0073	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Quilting 114	Wall cabinets over the work surface are mounted at 49" (1245 mm) above the finished floor to the bottom shelf.	\$804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0076	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Exercise 110	TV does not have the closed caption unit turned on.	\$36.303 (e)	Implement a policy to have the closed caption feature on during business hours.
ACS	0077	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Exercise 110	Soap dispenser is mounted beyond required reach allowed for approach provided and is mounted at 53.75" (1365 mm) above the finished floor	\$308.2.1	Lower or install soap dispenser at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0078	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Exercise 110	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 76" (1930 mm) above the finished floor.	\$308.3	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.3.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0083	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Arts and Crafts 108	Sink has unwrapped pipes.	§606.5	Cover (insulate) sink bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0084	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Arts and Crafts 108	Sink is mounted at 34.25" (870 mm) above the finished floor to the top.	§606.3.2	Relocate / rework sink and mount at 34" (863 mm) max. above the finished floor to top of counter. <i>This dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.</i>
ACS	0085	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Arts and Crafts 108	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 53.5" (1359 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991</i>
ACS	0049	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0050	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0055	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Men's Accessible Restroom on Left Side of Lobby	Bench is mounted at 20.25" (514 mm) above the finished floor.	§903.5	We recommend reworking bench to provide 17-19" (431mm-485 mm) above the finished floor seat height with armrests and supportive backrest design (for ease in sitting/standing) (2010 ADA Fig.903.4).
ACS	0060	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0061	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0067	Senior Services	New Beginnings Neighborhood Senior Center	66 Brooks Drive Fairburn, GA 30213		1st	COM SPC	Women's Accessible Restroom on Left Side of Lobby	Bench is mounted at 20.25" (514 mm) above the finished floor.	§903.5	We recommend reworking bench to provide 17-19" (431mm-485 mm) above the finished floor seat height with armrests and supportive backrest design (for ease in sitting/standing) (2010 ADA Fig.903.4).
ACS	0001	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Multi-Purpose Room No. 124	Trash bin and counter encroach sign clear floor space.	703.4.2	Remove trash bin and counter to provide a clear floor space of 18" (455 mm) minimum by 18" (455 mm) minimum, centered on the tactile characters.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0017	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Accessible Parking Spaces	Accessible parking space does not have signage indicating the penalty for illegal use of the parking space.		Install sign indicating accessible parking displaying the international symbol of accessibility, bearing the caption "Parking by disabled Permit only" and the penalty for illegal use of this space, and mount at 60" (1524 mm) min. above the finish floor. Post sign as required by Georgia law.
ACS	0018	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Path of travel to Outdoor Seating Area	The foot of the curb ramp is not flush.	§406.2	The adjacent surfaces at transitions from curb ramps to walks, gutters, and streets shall be at the same level (2010 ADA Fig. 406.2).
ACS	0020	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Path from Public Rights of Way to Designated Smoking Area	No maneuvering clearance on the pull side of the gate leading to Public Rights-of-Way	§404.2.4	Rework slab adjacent to gate to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0021	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Path from Public Rights of Way at South East Corner	No maneuvering clearance on the pull side of the gate leading to Public Rights-of-Way	§404.2.4	Rework slab adjacent to gate to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0002	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Multi-Purpose Room No. 124	Tables have a non-compliant 16" (406 mm) horizontal projection.	§902.2	Replace tables to provide 5% accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0003	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Multi-Purpose Room No. 124	Hand sanitizer is mounted beyond required reach allowed for approach provided and is mounted at 51" (1295 mm) above the finished floor.	§308.2.1	Lower or install hand sanitizer dispenser at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0004	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Multi-Purpose Room No. 124	TV provided does not have the closed caption feature turned on.	§36.303(e)	Implement a policy to have the closed caption feature on during business hours.
ACS	0005	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Men's Restroom	Maneuvering clearance on the push side is 46" (1168 mm) wide for a parallel hinge approach.	§404.2.4	Relocate drinking fountain to provide the required 22" (560 mm) min. maneuvering clearance on the push side of the door, for a parallel hinge approach and 48" (1220 mm) min. deep clear floor area (For doors with latch and closer) (2010 ADA Fig. 404.2.4.1)
ACS	0006	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Men's Restroom	Toilet seat cover dispenser behind the water closet.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed approach to object. If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar . If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3) (2010 ADA Fig. 308.2.1).
ACS	0007	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Men's Restroom	Soap dispenser is mounted beyond required reach allowed for approach provided and is mounted at 55" (1397 mm) above the finished floor.	§308.2.1	Lower or install soap dispenser at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0008	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Men's Restroom	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 52" (1321 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0009	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Women's Restroom	Maneuvering clearance on the push side is 44.5" (1130 mm) wide for a parallel hinge approach.	§404.2.4	Relocate drinking fountain to provide the required 22" (560 mm) min. maneuvering clearance on the push side of the door, for a parallel hinge approach and 48" (1220 mm) min. deep clear floor area (For doors with latch and closer) (2010 ADA Fig. 404.2.4.1)
ACS	0010	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Women's Restroom	Toilet seat cover dispenser is mounted behind the water closet.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed approach to object. If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar . If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3) (2010 ADA Fig. 308.2.1).
ACS	0011	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Women's Restroom	Soap dispenser is mounted beyond required reach allowed for approach provided and is mounted at 51" (1295 mm) above the finished floor.	§308.2.1	Lower or install soap dispenser at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0012	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Women's Restroom	Furniture and planter encroach over maneuvering clearance on the pull side of the door.	§404.2.4	Relocate furniture and planter to provide the required 54" (1370 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0013	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Ceramic 113	Tables encroaches passage width reducing it to 24" (610 mm).	§403.5.1	Relocate table to provide a 36" (914 mm) min. clear width continuously (2010 ADA Fig. 403.5.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0014	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Ceramic 113	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 54" (1372 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0015	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Classroom 115	TV provided does not have the closed caption feature turned on.	§36.303(e)	Implement a policy to have the closed caption feature on during business hours.
ACS	0016	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Lounge	TV provided does not have the closed caption feature turned on.	§36.303(e)	Implement a policy to have the closed caption feature on during business hours.
ACS	0019	Senior Services	New Horizon Neighborhood Senior Center	745 Orr Street NW Atlanta, GA 30314		1st	COM SPC	Designated Smoking Area	Bench does not provide the required clear floor space	§903.2	Rework area or relocate bench to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space positioned at the end of the bench seat parallel to the short axis of the bench.
ACS	0001	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0001	Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	First accessible parking space from left to right does not have an access aisle.	§502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).
ACS	0003	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	Second accessible parking space from left to right has a 2.5 % non-compliant running slope.	§504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	0006	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	Second access aisle from left to right has up to a 2.8 % non-compliant running slope.	§502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	0007	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	Third access aisle from left to right has up to a 2.3 % non-compliant running slope.	§502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	0008	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	Third access aisle from left to right has a vertical change in level and an opening that is more than 1" (26 mm) wide at transition to sidewalk	§303.2, §303.2	Rework area and provide a 0.25" (6 mm) max. vertical change of level, with a slope no greater than 1:2 and a 0.5" (12 mm) max. wide opening perpendicular to the dominant direction of travel (2010 ADA Fig.302.3),(2010 ADA Fig. 303.2).
ACS	0009	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	Fourth access aisle from left to right has a 2.4 % non-compliant surface slope.	§502.4	Rework or repave to provide a van-accessible parking space 96" (2438 mm) min. wide and a 96" (2438 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions.
ACS	0010	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	Fourth access aisle from left to right has a vertical change in level and an opening that is more than 1" (26 mm) wide at transition to sidewalk	§303.2, §303.2	Rework area and provide a 0.25" (6 mm) max. vertical change of level, with a slope no greater than 1:2 and a 0.5" (12 mm) max. wide opening perpendicular to the dominant direction of travel (2010 ADA Fig.302.3),(2010 ADA Fig. 303.2).
ACS	0011	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0002	1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 4.1 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0012	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 4.0 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0013	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 4.2 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0014	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.2 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0015	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.5 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0016	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.0 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0017	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 2.2 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0018	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 2.7 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0019	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 2.3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0020	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 2.4 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0021	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route in Front of Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0022	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0003	Grade	COM SPC	Passenger Loading Zone	Passenger loading zone does not have signage displaying the international symbol of accessibility.	\$216.2	Provide a sign indicating passenger loading zone, displaying the International symbol of accessibility.
ACS	0023	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0004	1st	COM SPC	Accessible Route from Passenger Loading Zone to Main Entrance	The surface of the accessible route has an opening that is 1" (25 mm) wide.	\$302.3	Rework area to provide a 0.5" (12 mm) max. wide opening perpendicular to the dominant direction of travel (2010 ADA Fig. 302.3).
ACS	0028	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0006	1st	COM SPC	Unisex Accessible Restrooms	Door has a non-compliant opening force of 20 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0037	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0007	1st	COM SPC	Quiet Room in Front of Unisex Restroom	Permanent room identifying signage is mounted at 62.5" (1588 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0039	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0008	1st	COM SPC	Lounge	Permanent room identifying signage does not have Braille or raised characters.	\$703.3	Provide signage displaying raised characters on non-glare contrasting surface, Grade 2 Braille text of same information.
ACS	0042	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0009	1st	COM SPC	Office	Permanent room identifying signage is mounted at 62" (1575 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0043	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Office	Desk and chairs encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate desk and chairs to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area (2010 ADA Fig. 404.2.4.1).
ACS	0051	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0013	1st	COM SPC	Computer Room	Permanent room identifying signage is mounted at 62.25" (1581 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0054	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268			COM SPC	Computer Room	Computers do not appear to have accessible software.	\$508	Title II of the ADA requires that programs, services and activities offered by public agencies be accessible to persons with disabilities. Section 508 of the Rehabilitation Act of 1973 provides guidelines for developing, procuring, maintaining, or using electronic and information technology. Per Section 508 ensure computer provides accessible hardware/software
ACS	0055	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0014	1st	COM SPC	Exercise Room	Permanent room identifying signage is mounted at 62.25" (1581 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0056	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Exercise Room	Vision light is mounted at 43.25" (1099 mm). above the finished floor.	\$404.2.3	Lower or install vision light at 43" (1090 mm) maximum above the finish floor. <i>This dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.</i>
ACS	0058	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Exercise Room	Equipment encroaches passage width reducing it to 24" (610 mm).	\$403.5.1	Relocate equipment to provide a 36" (914 mm) min. clear width continuously (2010 ADA Fig. 403.5.1).
ACS	0065	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0015	1st	COM SPC	Arts & Craft Room	Permanent room identifying signage is mounted at 62.25" (1581 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0066	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Arts & Craft Room	Furniture encroaches over maneuvering clearance on the pull side of the door reducing it to 8" (203 mm)	\$404.2.4	Relocate furniture to provide a 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0074	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0016	1st	COM SPC	Billiards	Permanent room identifying signage is mounted at 62.5" (1588 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0075	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0017	1st	COM SPC	Aerobics Room	Permanent room identifying signage is mounted at 62.5" (1588 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0076	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0018	1st	COM SPC	Quilting Room	Permanent room identifying signage is mounted at 62.5" (1588 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0078	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0019	1st	COM SPC	Men's Accessible Restroom	Permanent room identifying signage is mounted on the hinge side of the door.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0079	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Maneuvering clearance on the push side is 47" (1194 mm) deep for a parallel hinge approach.	\$404.2.4	Relocate drinking fountains to provide the required 22" (560 mm) min. maneuvering clearance on the push side of the door, for a parallel hinge approach and 48" (1220 mm) min. deep clear floor area (For doors with latch and closer) (2010 ADA Fig. 404.2.4.1)
ACS	0088	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Door has a non-compliant opening force of 10 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0099	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0021	1st	COM SPC	Multipurpose Room	Signage containing tactile characters does not have the required clear floor space.	\$703.4.2	Relocate furniture to ensure that a clear floor space of 18" (455 mm) min. by 18" (455 mm) min. centered on the tactile characters, is provided beyond the arc of the door swing, between the closed position and 45° open position (2010 ADA Fig. 703.4.2).
ACS	0100	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Multipurpose Room	Permanent room identifying signage is mounted at 62.25" (1581 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0111	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0023	1st	COM SPC	Outdoor Seating Area	Furniture encroaches over maneuvering clearance on the push side of the door.	\$404.2.4	Relocate furniture to provide the required 12" (304 mm) min. maneuvering clearance and 48" (1220 mm) depth on the push side of the door handle side (2010 ADA Fig. 404.2.4.1).
ACS	0112	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Door Leading to Outdoor Seating Area	Door has a non-compliant opening force of lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0116	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0024	1st	COM SPC	Patio	Door has a non-compliant opening force of 30 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0117	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0025	1st	COM SPC	Walkway Leading to Gazebo	Accessible route has a non-compliant running slope of 6.3 %.	\$403.3	Rework or repave accessible route to provide a running slope not exceeding 5%.
ACS	0118	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Walkway Leading to Gazebo	Accessible route has a non-compliant running slope of 5.1 %.	\$403.3	Rework or repave accessible route to provide a running slope not exceeding 5%.
ACS	0119	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Walkway Leading to Gazebo	Accessible route has a non-compliant running slope of 6.2 %.	\$403.3	Rework or repave accessible route to provide a running slope not exceeding 5%.
ACS	*0002	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	First accessible parking space from left to right has up to a 2.8 % non-compliant running slope.	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0004	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	First access aisle from left to right has up to a 3 % non-compliant running slope.	\$502.4	Rework or repave to provide a van-accessible parking space 96" (2438 mm) min. wide and a 96" (2438 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions.
ACS	*0005	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		Grade	COM SPC	Seven Accessible Parking Spaces in Front of Main Entrance	Third accessible parking space from left to right has up to a 2.7 % non-compliant running slope.	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	0026	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0005	1st	COM SPC	Corridor on the Left Side of Reception	Drinking fountain water flow is less than 4" (102 mm) high.	\$602.6	Adjust to provide a flow of water at least 4" (101 mm) high so as to allow the insertion of a cup under it.
ACS	0027	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Corridor on the Left Side of Reception	Hand sanitizer is mounted beyond required reach allowed for approach provided and is mounted at 52.5" (1334 mm) above the finished floor	\$308.2.1	Lower or install hand sanitizer dispenser at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0029	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Unisex Accessible Restrooms	Toilet seat cover dispenser is mounted beyond reach ranges at 48" (1219 mm) above the finished floor and is mounted behind the water closet.	\$308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0030	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Unisex Accessible Restrooms	Lavatory mirror is mounted at 41" (1041 mm) above the finished floor to bottom edge of its reflecting surface.	§603.3	Lower lavatory mirror to 40" (1016 mm) max. above the finished floor to bottom edge of its reflecting surface.
ACS	0031	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Unisex Accessible Restrooms	Lavatory is 38.75" (984 mm) from side wall.	§604.8.1.1	Rework partitions and/or fixtures to provide a 60" by 56" (1524 mm by 1422 mm) min. accessible toilet clear floor space for a wall mounted water closet (2010 ADA Fig. 604.8.1.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0032	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Unisex Accessible Restrooms	Water closet rear wall grab bar is mounted at 36.75" (933 mm) above the finished floor to the top of the gripping surface.	§604.5.2	Install a 36" (914 mm) min. long rear wall grab bar that extends 24" (610 mm) min. from water closet centerline to the outer flange (on open side) of the grab bar and 12" (305 mm) min. from the water closet centerline to the inner flange (on wall side) of grab bar, mount between 33" and 36" (838 mm - 914 mm) above the floor to top of the gripping surface (2010 ADA Fig. 604.5.2)
ACS	0033	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Unisex Accessible Restrooms	Water closet side wall grab bar is mounted at 36.75" (933 mm) above the finished floor to the top of the gripping surface.	§604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33" - 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. (2010 ADA Fig. 604.5.1)
ACS	0034	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Unisex Accessible Restrooms	Toilet tissue dispenser is mounted at 41.5" (1054 mm) from rear wall to outer leading edge.	§604.9.6	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 14"-19" (381 mm to 1219 mm) above the finished floor to the dispenser outlet. If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3) (2010 ADA Fig. 604.7)
ACS	0035	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Unisex Accessible Restrooms	Water closet is centered at 18.5" (470 mm) from side wall	§604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2)
ACS	0036	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Unisex Accessible Restrooms	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 65" (1651 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0038	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Quiet Room in Front of Unisex Restroom	Brochure rack is mounted at 63.75" (1619 mm) above the finished floor to highest shelf.	§308.2.1	Lower or install brochure rack at 48" (1219 mm) max. above the finished floor to highest shelf (2010 ADA Fig. 308.2.1).
ACS	0040	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Lounge	Planter encroaches over telephone clear floor space.	§305.3	Relocate planter to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0041	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Lounge	Books are mounted beyond required reach allowed for approach provided.	§308.3.1	Implement policy to assist residents by retrieving books from inaccessible shelves or ensure books are made available at the counter if requested. Post signage displaying the International Symbol of Accessibility indicating that "Assistance is Available Upon Request" (§36.304 (f) and §36.305 (b) (3)).
ACS	0044	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268			COM SPC		Desk has a non-compliant clear floor space.	§902.2	Relocate furniture to provide seating with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance above the finished floor and a 17" (430 mm) horizontal projection.
ACS	0045	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Office	Telephone is mounted at 66.5" (1689 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0046	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0010	1st	COM SPC	Lobby	Chair encroaches over thermostat clear floor space.	§305.3	Relocate chair to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0047	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Lobby	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 59.5" (1511 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0048	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0011	1st	COM SPC	Corridor Leading to Quilting Room	Hand sanitizer is mounted beyond required reach allowed for approach provided and is mounted at 54.75" (1391 mm) above the finished floor	§308.2.1	Lower or install hand sanitizer at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0049	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Corridor Leading to Quilting Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 61.25" (1556 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0050	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0012	1st	COM SPC	SE Corridor	Shelf protrudes into walkway, projecting 10" (254 mm) from back wall, and is mounted at 46" (1168 mm) above the finished floor to its bottom leading edge.	§307.2b	Relocate and mount at or below 27" (685 mm) above the finished floor to its bottom leading edge, or place a cane-detectable element or barrier underneath (2010 ADA Fig. 307.2).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0052	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Computer Room	Furniture encroaches over telephone clear floor space.	§305.3	Relocate furniture to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0053	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Computer Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 60.25" (1530 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0057	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Exercise Room	Exercise machines and equipment have a non-compliant clear floor space.	§1004.1	Relocate exercise machines and equipment to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space, positioned for transfer or use by an individual seated in a wheelchair (2010 ADA Fig. 305.3, 305.5).
ACS	0059	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268			COM SPC	Exercise Room	Equipment encroaches into maneuvering clearance on the pull side of the door.	§404.2.4	Relocate equipment to provide a 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0060	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Exercise Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 60.5" (1537 mm) above the finished floor.	§308.2.1	Lower or install thermostat at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0061	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Exercise Room	Telephone is mounted at 54.5" (1384 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0062	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Exercise Room	Equipment encroaches over telephone clear floor space.	§305.3	Relocate equipment to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space at telephone (2010 ADA Figs. 305.3-305.5).
ACS	0063	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268			COM SPC	Exercise Room	Chairs encroach over maneuvering clearance on pull side of door.	§404.2.4	Relocate chair to provide a 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0064	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Exercise Room	Telephone is mounted at 54.5" (1384 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0067	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Arts & Craft Room	Furniture encroaches over thermostat clear floor space.	§305.3	Relocate furniture to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0068	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Arts & Craft Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 60.5" (1537 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0069	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Arts & Craft Room	Sink is mounted at 34.25" (870 mm) above the finished floor to the top.	§606.3.2	Relocate / rework sink and mount at 34" (863 mm) max. above the finished floor to top of counter. <i>This dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.</i>
ACS	0070	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268			COM SPC	Arts & Craft Room	Sink has unwrapped pipes.	§606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0071	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268			COM SPC	Arts & Craft Room	Equipment encroaches into sink clear floor space.	\$606.2	Relocate equipment to provide a 30" by 48" (762 mm by 1219 mm) min. lavatory clear floor space at sink (2010 ADA Fig. 305).
ACS	0072	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Arts & Craft Room	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 56.75" (1441 mm) above the finished floor to paper.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0073	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Arts & Craft Room	Telephone is mounted at 54.5" (1384 mm) above the finished floor to the highest operable part.	\$308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0077	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Quilting Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 60.75" (1543 mm) above the finished floor.	\$308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0080	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Locker mechanism requires pinching and tight grasping to operate.	\$309.4, \$225.2.1	Replace or retrofit bottom lockers with system operable with one hand, not requiring pinching, tight grasping or turning of the wrist to operate. 5% of lockers are required to be accessible.
ACS	0083	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Water closet side wall grab bar is mounted at 37" (940 mm) above the finished floor to the top of the gripping surface.	\$604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.1)
ACS	0084	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Toilet tissue dispenser is mounted over the side wall grab bar.	\$609.3	Relocate toilet tissue dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. or below at 1.5" (38 mm) min under sidewall grab bar (2010 ADA Fig. 609.3). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0085	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Toilet seat cover dispenser is mounted beyond reach ranges and is mounted behind the water closet.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)
ACS	0086	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Water closet is centered at 20.5" (521 mm) from side wall.	§604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0087	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Water closet rear wall grab bar is mounted at 36.75" (933 mm) above the finished floor to the top of the gripping surface.	§604.5.2	Install a 36" (914 mm) min. long rear wall grab bar that extends 24" (610 mm) min. from water closet centerline to the outer flange (on open side) of the grab bar and 12" (305 mm) min. from the water closet centerline to the inner flange (on wall side) of grab bar. Mount between 33" and 36" (838 mm - 914 mm) above the finished floor.
ACS	0089	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0020	1st	COM SPC	Women's Accessible Restroom	Locker mechanism requires pinching and tight grasping to operate.	§309.4, §225.2.1	Replace or retrofit bottom lockers with system operable with one hand, not requiring pinching, tight grasping or turning of the wrist to operate. 5% of lockers are required to be accessible.
ACS	0092	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Women's Accessible Restroom	Toilet seat cover dispenser is mounted beyond reach ranges and is mounted behind the water closet.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0093	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Women's Accessible Restroom	Water closet is centered at 20" (508 mm) from side wall.	§604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0094	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Women's Accessible Restroom	Water closet side wall grab bar is mounted at 37" (940 mm) above the finished floor to the top of the gripping surface.	§604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.1)
ACS	0095	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Women's Accessible Restroom	Toilet tissue dispenser is mounted over the side wall grab bar.	§609.3	Relocate toilet tissue dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. or below at 1.5" (38 mm) (2010 ADA Fig. 609.3). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and
ACS	0096	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Women's Accessible Restroom	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 60" (1524 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0097	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0021	1st	COM SPC	Corridor	Shelf protrudes into walkway, projecting 10" (254 mm) from back wall, and is mounted at 46" (1168 mm) above the finished floor to its bottom leading edge.	§307.2b	Relocate and mount at or below 27" (685 mm) above the finished floor to its bottom leading edge, or place a cane-detectable element or barrier underneath (2010 ADA Fig. 307.2).
ACS	0098	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Corridor	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 60.5" (1537 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0101	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Multipurpose Room	Couch encroaches over telephone clear floor space.	§305.3	Relocate couch or telephone to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0102	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Multipurpose Room	Telephone is mounted at 54.5" (1384 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0103	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Multipurpose Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 60.5" (1537 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0104	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268			COM SPC	Multipurpose Room	Food counter/tray slide is mounted at 35.75" (908 mm) above the finished floor to top.	§308.2.1	Rework tray slide so that a portion of the main counter is mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground.
ACS	0105	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Multipurpose Room	Hot water dispenser is mounted beyond required reach allowed for approach provided and is mounted at 50.75" (1289 mm) above the finished floor over an obstruction (counter)	§308.3.1	Lower or install dispenser at 48" (1219 mm) max. above the finished floor over an obstruction 34" (865 mm) max above finished floor and a 10" (255 mm) max reach depth for side approach to object (2010 ADA Fig. 308.3.1).
ACS	0106	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Multipurpose Room	Microwave is mounted beyond required reach allowed for approach provided and is mounted at 50.75" (1289 mm) above the finished floor over an obstruction (counter)	§308.3.1	Lower or install microwave at 48" (1219 mm) max. above the finished floor over an obstruction 34" (865 mm) max above finished floor and 10" (255 mm) max reach depth for side approach to object (2010 ADA Fig. 308.3.1).
ACS	0107	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Multipurpose Room	Table and trash bin encroaches over thermostat and light switch clear floor space.	§305.3	Relocate table and trash bin to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space at thermostat and at light switch (2010 ADA Figs. 305.3-305.5).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0109	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Stage at Multipurpose Room	Handrails are mounted at 33.5" (851 mm).	\$405.8	Provide handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment.
ACS	0110	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Stage at Multipurpose Room	TV encroaches top landing.	\$405.7.3	Relocate TV to provide 60" by 60" (1524 mm by 1524 mm) min. long landing at change of direction (2010 ADA Fig 405.7)
ACS	0113	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Outdoor Seating Area	Exit door does not have signage posted.	\$216.4	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0114	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Outdoor Seating Area	Tables have a non-compliant 15" (381 mm) horizontal projection.	\$902.2	Replace tables to provide (1) accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0115	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Outdoor Seating Area	Tables have a non-compliant 25.75" (654 mm) knee clearance.	\$902.2	Replace tables to provide (1) accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0122	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Walkway Leading to Gazebo	Accessible route has a non-compliant cross slope of 3.5 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0123	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Walkway Leading to Gazebo	Accessible route has a non-compliant cross slope of 4.5 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0124	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Walkway Leading to Gazebo	Accessible route has a non-compliant cross slope of 4.5 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0126	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0027	1st	COM SPC	Walkway Leading to Gazebo	Ramp with a slope of 12.5 % and extends 10' (3.048 m) does not have the required handrails.	\$405.8	For ramps rising over 6" (152 mm) provide handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment
ACS	0127	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0028	1st	COM SPC	Foyer	Door encroaches news paper dispenser and table clear floor space.	\$305.3	Relocate table and newspaper dispenser to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	*0108	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0022	1st	COM SPC	Stage at Multipurpose Room	Ramp with a slope of up to 8.1 % rises 12" (305 mm) and does not have handrails on both sides	\$405.8	For ramps rising over 6" (152 mm) provide handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment. Ensure that once the handrails are installed there is a minimum clearance of 36" (mm) between the inner face of the handrails.
ACS	0024	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route from Passenger Loading Zone to Main Entrance	Right bench clear floor space has a 3.1% cross slope.	\$903.2	We recommend reworking area or relocating bench to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space positioned at the end of the bench seat parallel to the short axis of the bench with slopes not exceeding 2% in all directions.
ACS	0025	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Accessible Route from Passenger Loading Zone to Main Entrance	Left bench clear floor space has a 4.1% cross slope.	\$903.2	We recommend reworking area or relocating bench to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space positioned at the end of the bench seat parallel to the short axis of the bench with slopes not exceeding 2% in all directions.
ACS	0081	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	\$604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0082	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Men's Accessible Restroom	Accessible compartment (stall) door does not have a self closing mechanism.	\$604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0090	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Women's Accessible Restroom	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	\$604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0091	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Women's Accessible Restroom	Accessible compartment (stall) door does not have a self closing mechanism.	\$604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0120	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Walkway Leading to Gazebo	Bench does not provide the required clear floor space	§903.2	We recommend reworking area or relocating bench to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space positioned at the end of the bench seat parallel to the short axis of the bench.
ACS	0121	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268	0026	1st	COM SPC	Walkway Leading to Gazebo	Bench is mounted at 15" (381 mm) above the finished floor.	§903.5	We recommend reworking bench to provide 17-19" (431 mm - 485 mm) above the finished floor seat height with armrests and supportive backrest design (for ease in sitting/standing) (2010 ADA Fig.903.4).
ACS	0125	Senior Services	Palmetto Neighborhood Senior Center	510 Turner Avenue Palmetto, GA 30268		1st	COM SPC	Walkway Leading to Gazebo	Bench does not provide the required clear floor space	§903.2	We recommend reworking area or relocating bench to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space positioned at the end of the bench seat parallel to the short axis of the bench.
ACS	0051	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Side Entrance	Carpet is not securely attached to the floor.	§302.2	Provide a securely attached carpet with a leveled loop or level cut pile, with texture height that is 0.5" (13 mm) max. and has a firm cushion pad or backing (2010 ADA Fig. 302.2).
ACS	0067	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0014	1st	COM SPC	East Side Entrance	Carpet is not securely attached to the floor.	§302.2	Provide a securely attached carpet with a leveled loop or level cut pile, with texture height that is 0.5" (13 mm) max. and has a firm cushion pad or backing (2010 ADA Fig. 302.2).
ACS	0076	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Anne Wood All-Purpose Room	Emergency exit door does not have Braille or raised characters and is mounted over the door leaf.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0089	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0018	1st	COM SPC	Emergency Exit next to Office	Emergency exit door does not have Braille or raised characters and is mounted over the door leaf.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).

Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0195	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0034	1st	COM SPC	Emergency exit adjacent to Manager's Office	Emergency exit door does not have Braille or raised characters and is mounted over the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0295	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0047	1st	COM SPC	Emergency Exit	Emergency exit door does not have Braille or raised characters and is mounted over the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0002	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Accessible Route From Public Rights-of-Way Leading to Main Entrance	Accessible route has a non-compliant running slope of 8.9 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0003	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Accessible Route From Public Rights-of-Way Leading to Main Entrance	Accessible route has a non-compliant running slope of 7.2 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0004	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Accessible Route From Public Rights-of-Way Leading to Main Entrance	Accessible route has a non-compliant running slope of 8.0 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0005	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Accessible Route From Public Rights-of-Way Leading to Main Entrance	Accessible route has a non-compliant running slope of 9.6 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0006	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Accessible Route From Public Rights-of-Way Leading to Main Entrance	Accessible route has a non-compliant running slope of 7.3 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0007	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Accessible Route From Public Rights-of-Way Leading to Main Entrance	Accessible route has a non-compliant running slope of 7 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0008	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0002	Grade	COM SPC	Accessible Route From Public Rights-of-Way Leading to Main Entrance	Does not provide clearance on the pull side of the door.	\$404.2.4	Widen path to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0010	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Gate to Parking Area	Accessible route has a non-compliant cross slope of 9.3 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0011	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Gate to Parking Area	Accessible route has a non-compliant running slope of 10.2 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0012	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Gate to Parking Area	Accessible route has a non-compliant running slope of 8.4 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0013	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Gate to Parking Area	Accessible route has a non-compliant running slope of 10.6 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0014	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Gate to Parking Area	Accessible route has a non-compliant running slope of 7.5 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0015	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0004	Grade	COM SPC	Driveway	Accessible route has a non-compliant cross slope of 8.5 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0016	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Driveway	Accessible route has a non-compliant running slope of 10.8 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0017	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Driveway	Accessible route has a non-compliant running slope of 9 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0018	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Driveway	Accessible route has a non-compliant running slope of 8.7 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0019	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Driveway	Accessible route has a non-compliant cross slope of 11.1 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0021	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 9.5 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0022	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 8 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0023	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 9.5 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0024	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 9.7 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0025	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant cross slope of 10.8 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0027	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant cross slope of 9 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0028	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 7.1 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0029	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 5.4 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0030	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant cross slope of 5.6 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0031	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 6.6 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0032	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 5.3 %.	§403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	0033	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0007	Grade	COM SPC	Path in Front of Main Entrance	The surface of the path is unstable, cracked and has loose material.	§302.1	Rework and clean sidewalk to provide a stable, firm, and slip- resistant floor surface.
ACS	0034	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path in Front of Main Entrance	Path has up to a 1.5" (38 mm) vertical change in level.	§303.2	Rework area and provide a 0.25" (6 mm) max. vertical change of level, with a slope no greater than 1:2 (2010 ADA Fig. 303.2).
ACS	0035	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path in Front of Main Entrance	Accessible route has a non-compliant cross slope of 2.8 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0036	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path in Front of Main Entrance	Accessible route has a non-compliant cross slope of 3.0 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0037	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path in Front of Main Entrance	Accessible route has a non-compliant cross slope of 2.4 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0038	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path in Front of Main Entrance	Accessible route has a non-compliant cross slope of 2.3 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0039	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0008	Grade	COM SPC	Main Entrance	Passenger loading zone does not have signage displaying the international symbol of accessibility.	§216.2	Provide a sign indicating passenger loading zone, displaying the International symbol of accessibility.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0040	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Main Entrance	There is no sign indicating accessible entrance.	§216	Post sign indicating accessible entrance displaying the International symbol of accessibility.
ACS	0042	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Main Entrance to Side Classrooms	walkway has a non-compliant vertical change in level.	§303.2	Rework area and provide a 0.25" (6 mm) max. vertical change of level, with a slope no greater than 1:2 (2010 ADA Fig. 303.2).
ACS	0043	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Main Entrance to Side Classrooms	Accessible route has a non-compliant cross slope of 7.2 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0044	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Main Entrance to Side Classrooms	Accessible route has a non-compliant cross slope of 2.7 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0045	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path from Main Entrance to Side Classrooms	Accessible route has a non-compliant cross slope of 3.0 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0046	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0010	Grade	COM SPC	Path in Front of Side Entrance	Accessible route has a non-compliant cross slope of 2.8 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0047	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path in Front of Side Entrance	Accessible route has a non-compliant cross slope of 3.0 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0048	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path in Front of Side Entrance	Accessible route has a non-compliant cross slope of 3.0 %.	§403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0049	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path in Front of Side Entrance	Ramp with a slope of 6% rises 7" (178 mm) and does not have the required handrails.	\$405.8	For ramps rising over 6" (152 mm) provide handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment.
ACS	0050	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0011	Grade	COM SPC	Side Entrance	Landing in front of side entrance has a 1" (25 mm) vertical change in level.	\$303.2	Rework area and provide a 0.25" (6 mm) max. vertical change of level, with a slope no greater than 1:2 or mitigate condition by means of a curb ramp, ramp or platform lift (2010 ADA Fig. 303.2).
ACS	0052	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0012	Grade	COM SPC	Four Accessible Parking Spaces	First parking space from right to left does not have signage indicating accessible parking.	\$502.6	Install signage indicating accessible parking that displays the international symbol of accessibility and mount at 60" (1524 mm) min. above the finished floor.
ACS	0053	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	First accessible parking space from right to left is faded.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0054	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	Access aisle is faded.	\$502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).
ACS	0055	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	Second accessible parking space from right to left does not have signage indicating accessible parking.	\$502.6	Install signage indicating accessible parking that displays the international symbol of accessibility and mount at 60" (1524 mm) min. above the finished floor.
ACS	0056	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	Second accessible parking space from right to left is faded.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0057	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	Second access aisle from right to left is faded.	\$502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0058	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	Third accessible parking space from right to left does not have signage indicating accessible parking.	\$502.6	Install signage indicating accessible parking that displays the international symbol of accessibility and mount at 60" (1524 mm) min. above the finished floor.
ACS	0059	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	Third accessible parking space from right to left is faded.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0060	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	Third access aisle from right to left is faded.	\$502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).
ACS	0062	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	Fourth accessible parking space from right to left has no signage indicating accessible parking.	\$502.6	Install signage indicating accessible parking that displays the international symbol of accessibility and mount at 60" (1524 mm) min. above the finished floor.
ACS	0063	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path of Travel from Four Accessible Parking Spaces to Side Entrance	There is no signage posted indicating the location of an accessible entrance.	\$216.6	Post signage indicating location of the accessible entrance serving the facility. If sign is to be placed overhead it shall have a minimum character height of 3" (76 mm).
ACS	0064	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0013	Grade	COM SPC	Path of Travel from Four Accessible Parking Spaces to Side Entrance	Ramp has a slope of 8.0 % and does not have the required handrails.	\$405.8	Install handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment.
ACS	0066	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path of Travel from Four Accessible Parking Spaces to Side Entrance	Accessible route has a non-compliant cross slope of 2.7 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0068	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	East Side Entrance	Door has a non-compliant opening force of 10 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0069	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0015	1st	COM SPC	Anne Wood All-Purpose Room	Permanent room identifying signage does not have Braille or raised characters and is mounted on the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0077	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Anne Wood All-Purpose Room	Door vision light is mounted at 48.5" (1232 mm).	\$404.2.11	Rework/replace door to provide vision lights mounted at 43" (1090 mm) maximum above the finish floor.
ACS	0090	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0019	1st	COM SPC	Second Office	Door vision light is mounted at 48.5" (1232 mm).	\$404.2.11	Rework/replace door to provide vision lights mounted at 43" (1090 mm) maximum above the finish floor.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0091	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Second Office	Furniture encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate furniture to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0092	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0020	1st	COM SPC	Men's Accessible Restroom	Water heater encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate water heater to provide the required 24" (609 mm) min. maneuvering clearance on the pull side of the door for a parallel latch side approach and 54" (1370 mm) min. deep clear floor area (2010 ADA Fig. 404.2.4.1).
ACS	0093	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Door has a non-compliant opening force of 12 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0115	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Toilet tissue dispenser is mounted over the side wall grab bar.	\$609.3	Relocate toilet tissue dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those
ACS	0116	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0021	1st	COM SPC	Women's Accessible Restroom	Door has a non-compliant opening force of 12 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0129	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Toilet seat cover dispenser is mounted over the side wall grab bar.	\$609.3	Relocate toilet seat cover dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those
ACS	0132	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0023	1st	COM SPC	Game Room Number 8	Permanent room identifying signage does not have Braille or raised characters and is mounted over the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0133	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Door vision light is mounted at 50.25" (1276 mm) .	\$404.2.11	Rework/replace door to provide vision lights mounted at 43" (1090 mm) maximum above the finish floor.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0149	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Ceramics Room Number 7	Permanent room identifying signage does not have Braille or raised characters and is mounted over the door leaf.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0150	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Ceramics Room Number 7	Vision light is mounted at 50" (1270 mm).	§404.2.11	Rework/replace door to provide vision lights mounted at 43" (1090 mm) maximum above the finish floor.
ACS	0155	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Ceramics Room Number 7	Trash can encroaches over maneuvering clearance on the pull side of the door.	§404.2.4	Relocate trash to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0156	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0026	1st	COM SPC	Travel office Room Number 6	Permanent room identifying signage does not have Braille or raised characters and is mounted over the door leaf.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0158	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Travel office Room Number 6	Door has a non-compliant opening force of 10 lbf.	§404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0159	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Travel office Room Number 6	Door vision light is mounted at 50" (1270 mm).	§404.2.11	Rework/replace door to provide vision lights mounted at 43" (1090 mm) maximum above the finish floor.
ACS	0162	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0027	1st	COM SPC	Staff Lounge	Permanent room identifying signage does not have Braille or raised characters.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0163	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0028	1st	COM SPC	Hat Room Number 5	Permanent room identifying signage does not have Braille or raised characters and is mounted over the door leaf.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0164	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Hat Room Number 5	Door vision light is mounted at 50" (1270 mm).	§404.2.11	Rework/replace door to provide vision lights mounted at 43" (1090 mm) maximum above the finish floor.
ACS	0165	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0029	1st	COM SPC	Multipurpose Room Number 4	Permanent room identifying signage does not have Braille or raised characters and is mounted over the door leaf.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0166	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Multipurpose Room Number 4	Door vision light is mounted at 50" (1270 mm).	\$404.2.11	Rework/replace door to provide vision lights mounted at 43" (1090 mm) maximum above the finish floor.
ACS	0167	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Multipurpose Room Number 4	Door has a non-compliant opening force of 10 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0170	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0030	1st	COM SPC	Healthy Cooking and Sewing Room Number 3	Permanent room identifying signage does not have Braille or raised characters and is mounted over the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0178	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0031	1st	COM SPC	Computer Room Number 2	Permanent room identifying signage does not have Braille or raised characters and is mounted over the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0180	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Computer Room Number 2	Door vision light is mounted at 49.75" (1264 mm).	\$404.2.11	Rework/replace door to provide vision lights mounted at 43" (1090 mm) maximum above the finish floor.
ACS	0181	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Computer Room Number 2	Door has a non-compliant opening force of 12 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0184	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0032	1st	COM SPC	Room Number 1	Permanent room identifying signage does not have Braille or raised characters and is mounted over the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0189	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Number 1	Table encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate table to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0192	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Number 1	Door has a non-compliant opening force of 9 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0193	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0033	1st	COM SPC	Manager's Office	There is no permanent room identifying signage does not have Braille or raised characters.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0194	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Manager's Office	Furniture encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate furniture to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0196	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Emergency exit adjacent to Manager's Office	Door has a non-compliant opening force of 14 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0198	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0036	1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Door has a non-compliant opening force of 12 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0199	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Maneuvering clearance on the pull side of the door is 47" (1194 mm) wide for a parallel latch approach.	\$404.2.4	Install an automatic door opener or rework door side partition to provide the required 24" (609 mm) min. maneuvering clearance on the pull side of the door for a parallel latch side approach and 54" (1370 mm) min. deep clear floor area (For door with a closer) (2010 ADA Fig. 404.2.4.1).
ACS	0209	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Toilet seat cover dispenser is mounted over the side wall grab bar.	\$609.3	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0225	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Dining Area	Handrails are mounted at 1.25" (32 mm) clear from the back wall.	§505.5	Relocate/replace handrails and mount at 1.5" (38 mm) clear from the back wall (2010 ADA Fig. 609.3).
ACS	0226	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Dining Area	Handrails do not have handrail extensions.	§505.10.1	Provide handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment (2010 ADA Fig. 505.10.1)
ACS	0227	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Dining Area	Ramp with a change in direction has a 41" by 42" (1041 by 1067 mm) wide landing.	§405.7.4	Rework ramp to provide 60" by 60" (1524 mm by 1524 mm) min. long landing, for ramps with a change of direction and runs rising over 30" (762 mm) (2010 ADA Fig. 405.7).
ACS	0230	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0040	1st	COM SPC	Men's Restroom	Door has a non-compliant opening force of 12 lbf.	§404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0231	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Door closing time is less than 5 seconds.	§404.2.8.1	Provide a sweep period of 5 seconds min. measured from 90° open position to a position of 12° from door latch.
ACS	0246	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0041	1st	COM SPC	Women's Accessible Restroom	Door has a non-compliant opening force of 14 lbf.	§404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0247	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Door closing time is less than 5 seconds.	§404.2.8.1	Provide a sweep period of 5 seconds min. measured from 90° open position to a position of 12° from door latch.
ACS	0248	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Maneuvering clearance on the pull side of the door is 37.5" (952 mm) wide for a parallel latch approach due to privacy partition.	§404.2.4	Install an automatic door opener or rework door side partition to provide the required 24" (609 mm) min. maneuvering clearance on the pull side of the door for a parallel latch side approach and 54" (1370 mm) min. deep clear floor area (For door with a closer) (2010 ADA Fig. 404.2.4.1). Alternative is to provide an automatic door opener.
ACS	0251	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Lavatory does not provide the required knee clearance due to water heater.	§404.2.4	Relocate water heater to provide the required 27" (685 mm) min. knee clearance above the finished floor to bottom leading edge of fixture at an 8" (203 mm) min. horizontal projection (2010 ADA Fig. 306.3).
ACS	0262	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0043	1st	COM SPC	Room Across from William Bridge Room	Non-compliant knob-type door hardware, requiring grasping and turning of the wrist to operate.	§404.2.7	Replace or retrofit with system operable with one hand, not requiring pinching, tight grasping or turning of the wrist to operate.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0263	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Across from William Bridge Room	Does not have permanent room identifying signage does not have Braille or raised characters.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0264	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Across from William Bridge Room	Vision light is mounted at 57.75" (1467 mm)	§404.2.11	Replace vision light with the bottom located 43" (1090 mm) maximum above the finish floor.
ACS	0270	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0044	1st	COM SPC	William "Bill" Marshall Bridge Room	Permanent room identifying signage does not have Braille or raised characters.	§703.3	Provide signage displaying raised characters on non-glare contrasting surface, Grade 2 Braille text of same information.
ACS	0271	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Vision light is mounted at 58" (1473 mm).	§404.2.11	Replace vision light with the bottom located 43" (1090 mm) maximum above the finish floor.
ACS	0272	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Non-compliant knob-type door hardware, requiring grasping and turning of the wrist to operate.	§404.2.7	Replace or retrofit with system operable with one hand, not requiring pinching, tight grasping or turning of the wrist to operate.
ACS	0281	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0045	1st	COM SPC	Music Room	Room does not have permanent room identifying signage.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0282	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Music Room	Non-compliant knob-type door hardware, requiring grasping and turning of the wrist to operate.	§404.2.7	Replace or retrofit with system operable with one hand, not requiring pinching, tight grasping or turning of the wrist to operate.
ACS	0283	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Music Room	Vision light is mounted at 58" (1473 mm).	§404.2.11	Replace vision light with the bottom located 43" (1090 mm) maximum above the finish floor.
ACS	0291	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0046	1st	COM SPC	Waiting Room	There is no permanent room identifying signage with Braille or raised characters.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0292	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Waiting Room	Non-compliant knob-type door hardware, requiring grasping and turning of the wrist to operate.	§404.2.7	Replace or retrofit with system operable with one hand, not requiring pinching, tight grasping or turning of the wrist to operate.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0293	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Waiting Room	Vision light is mounted at 58" (1473 mm).	§404.2.11	Replace vision light with the bottom located 43" (1090 mm) maximum above the finish floor.
ACS	0296	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0048	Grade	COM SPC	Three Accessible Parking Spaces on South Side	First accessible parking space from left to right does not have signage indicating accessible parking.	§502.6	Install signage indicating accessible parking that displays the international symbol of accessibility and mount at 60" (1524 mm) min. above the finished floor.
ACS	0300	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Three Accessible Parking Spaces on South Side	Access aisle is faded.	§502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).
ACS	0301	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Three Accessible Parking Spaces on South Side	The surface of the second accessible parking space from left to right is cracked and has loose material.	§302.1	Rework and clean sidewalk to provide a stable, firm, and slip-resistant floor surface. With surface slope not exceeding 2% in all directions
ACS	0302	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Three Accessible Parking Spaces on South Side	Second accessible parking space from left to right has a 0.75" (19 mm) vertical change in level.	§303.2	Rework area and provide a 0.25" (6 mm) max. vertical change of level, with a slope no greater than 1:2 (2010 ADA Fig. 303.2).
ACS	0303	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Three Accessible Parking Spaces on South Side	Second accessible parking space from left to right is faded.	§502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0304	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Three Accessible Parking Spaces on South Side	The surface of the second access aisle from left to right is unstable and has loose material.	§302.1	Rework and clean sidewalk to provide a stable, firm, and slip-resistant floor surface.
ACS	0305	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Three Accessible Parking Spaces on South Side	Second access aisle from left to right is faded.	§502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).
ACS	0306	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0049	Grade	COM SPC	Three Accessible Parking Spaces on South Side	Accessible parking spaces are not located on the shortest route to the Main Entrance.	§502.3.1	We recommend relocating the accessible parking spaces to the area in front of the main entrance, and provide accessible parking spaces that are 96" (2438 mm) min. wide with a 60" (15258 mm) min. wide access aisle and surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0307	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0050	Grade	COM SPC	Entrance on South Side	No sign indicating location of accessible entrance.	216.6	Post sign with international symbol of accessibility indicating location of accessible entrance.
ACS	0308	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0051	Grade	COM SPC	Striped Path to Accessible Entrance	Accessible route has a non-compliant cross slope of 3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	*0001	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0001	Grade	COM SPC	Accessible Route From Public Rights-of-Way Leading to Main Entrance	Accessible route has a non-compliant running slope of 8.5 %.	\$403.3	The facility provides pedestrian access from Public Rights-of-Way. The surface slopes exceed requirements, it is structurally impracticable to re-grade the entire site due to the unique characteristics of the terrain. An alternative is relocating the accessible entrance to west gate, providing a switchback ramp over the grass area that is adjacent to the vehicular entrance at Danforth Rd SW, and connecting with the access aisle at the accessible parking spaces to the main entrance.
ACS	*0009	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0003	Grade	COM SPC	Path from Gate to Parking Area	Accessible route has a non-compliant cross slope of 10.2 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	*0020	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0005	Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 10 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	*0026	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0006	Grade	COM SPC	Path from Driveway to Main Entrance	Accessible route has a non-compliant running slope of 9 %.	\$403.3	Provide a switchback ramp. Alternative is to provide accessible entrance through west entrance.
ACS	*0041	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0009	Grade	COM SPC	Path from Main Entrance to Side Classrooms	walkway has a non-compliant vertical change in level.	\$302.1	Rework and clean sidewalk to provide a stable, firm, and slip-resistant floor surface.
ACS	*0061	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Four Accessible Parking Spaces	Fourth accessible parking space from right to left has up to 2.5 % non-compliant running slopes.	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0065	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Path of Travel from Four Accessible Parking Spaces to Side Entrance	Ramp with a slope of 6.3 % that extends 10 ft (3.04 m), and does not have the required handrails.	\$405.8	Install handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment.
ACS	*0297	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Three Accessible Parking Spaces on South Side	First accessible parking space from left to right needs to be restriped.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	*0298	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Three Accessible Parking Spaces on South Side	First accessible parking space from left to right has a 2.6 % non-compliant surface slope.	\$502.4	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0299	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Three Accessible Parking Spaces on South Side	First access aisle from left to right has a 2.9 % non-compliant surface slope.	\$502.4	Rework or repave to provide an access aisle with surface slope not exceeding 2% in all directions.
ACS	0070	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Anne Wood All-Purpose Room	Shelf is mounted beyond required reach allowed for approach provided and is mounted at 64" (1626 mm) above the finished floor.	\$603.4	Lower or install shelf between at 48" (1219 mm) max. above the finished floor for forward approach to object

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0071	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Anne Wood All-Purpose Room	Tables have a non-compliant 26.5" (673 mm) knee clearance.	\$902.2	Replace tables to provide accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0072	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Anne Wood All-Purpose Room	Sink does not have the required knee clearance.	\$804.3.1	Rework sink to provide a 27" (685 mm) min. knee clearance above the finished floor to bottom leading edge of fixture at an 8" (203 mm) min. horizontal projection (2010 ADA Fig. 306.3)
ACS	0073	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Anne Wood All-Purpose Room	Sink is mounted at 41" (1041 mm) above the finished floor to top of rim.	\$804.4	Relocate and/or mount sink at 34" (863 mm) max. above the finished floor to top of rim.
ACS	0074	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Anne Wood All-Purpose Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 59.5" (1511 mm) above the finished floor.	\$308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0075	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Anne Wood All-Purpose Room	Trash bin encroaches over thermostat clear floor space.	\$305.3	Relocate trash bin to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (ADAAG Figs. 305.3-305.5).
ACS	0078	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0016	1st	COM SPC	Gym	Desk encroaches passage width to clothes rod reducing it to less than 36" (914 mm).	\$403.5.1	Relocate desk to provide a 36" (914 mm) min. clear width continuously (2010 ADA Fig. 403.5.1).
ACS	0079	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Gym	Clothes rod is mounted beyond required reach allowed for approach provided and is mounted at 53.75" (1365 mm) above the finished floor.	\$308.2.1	Lower or install accessible clothes rod at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(f) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0080	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Gym	Exercise machines and equipment have a non-compliant clear floor space.	\$1004.1	Relocate exercise machines and equipment to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space, positioned for transfer or use by an individual seated in a wheelchair (2010 ADA Fig. 305.3, 305.5).
ACS	0081	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Gym	Exercise equipment encroaches over sound system clear floor space.	\$305.3	Relocate exercise equipment to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (ADAAG Figs. 305.3-305.5).
ACS	0082	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Gym	Sound system is mounted beyond required reach allowed for approach provided and is mounted at 64" (1626 mm) above the finished floor.	\$308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0083	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Gym	Fan control is mounted beyond required reach allowed for approach provided and is mounted at 70" (1778 mm) above the finished floor.	\$308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0084	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0017	1st	COM SPC	Office	Door vision light is mounted at 48.5" (1232 mm).	\$404.2.11	Rework/replace door to provide vision lights mounted at 43" (1090 mm) maximum above the finish floor.
ACS	0085	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Office	Reception counter is mounted at 36.25" (921 mm) above the finished floor.	\$904.4.1	Provide an alternative counter or rework reception counter to provide a portion that is 36" (914 mm) min. long, mounted at 36" (914 mm) max. above the finished floor to the top. This dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section.
ACS	0086	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Office	Fan control is mounted beyond required reach allowed for approach provided and is mounted at 70" (1778 mm) above the finished floor.	\$308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0087	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Office	Time stamp machine protrudes into walkway, projecting 7" (178 mm) from back wall, and is mounted at 40" (1016 mm) above the finished floor to its bottom leading edge.	\$307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0088	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Office	Tables have a non-compliant 26.75" (679 mm) knee clearance .	§902.2	Provide seating with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance above the finished floor and a 17" (430 mm) horizontal projection.
ACS	0094	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Hand dryer protrudes into walkway, projecting 6" (152 mm) from back wall, and is mounted at 45.25" (1149 mm) above the finished floor to its bottom leading edge.	§307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0095	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 59" (1499 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0096	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Paper towel dispenser protrudes into walkway, projecting 11" (279 mm) from back wall, and is mounted at 53.25" (1353 mm) above the finished floor to its bottom leading edge.	§307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0097	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Transfer shower controls are mounted on the wrong wall.	§608.5.1	Mount shower controls on the side wall opposite to the seat, between 38" (965 mm) min. - 48" (1220 mm) max. above the finished floor to the highest operable part and at 15" (380 mm) from centerline to the edge of shower.
ACS	0098	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Transfer shower grab bar is mounted at a point of 25.5" (648 mm) from the control wall	§608.3.1	Install grab bars across the control wall and back wall to a point 18" (457 mm) from the control wall; and mount between 33" and 36" (838 mm- 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig.608.3.1).
ACS	0099	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Shower head is a fixed-type unit.	§607.6	Replace or install additional shower spray unit with a hose 59" (1500 mm) min. long that serves both as a fixed and hand-held unit. Shower spray unit shall have an on/off control with a non-positive shut-off and deliver water at 120 F maximum.
ACS	0100	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Transfer shower stall is 34.25" by 54.75" (870 by 1391 mm) and does not have the required clear floor space.	§608.2.1	Reconfigure room's fixtures and/or offset partitions to provide a 36" by 36" (914 mm by 914 mm) shower stall with the required 36" by 48" (914 mm by 1219 mm) min. clear floor space (2010 ADA Fig. 608.2.1).
ACS	0101	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Transfer seat does not extend up to a point 3" (75 mm) max. from the shower compartment entry	§610.3	Provide an L-shaped seat with the front edge mounted at 15"-16" (380 mm - 405 mm) max. from the wall, the end of the "L" shape shall be 22"-23" (560 mm - 585 mm) max. long and the front edge of the "L" portion 14"-15" (355 mm - 380 mm) max. from the wall.
ACS	0102	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	The back of the transfer seat is 3" (75mm) from back wall.	§610.3.2	Provide an L-shaped seat that extends up to 3" (75 mm) max. from the shower compartment entry, that is recessed 2.5" (63 mm) max. from the seat wall and 1.5" (38 mm) max. from the rear edge of the L-portion of the seat (2010 ADA Fig. 610.3.2).
ACS	0103	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Urinal is mounted in a 34.25" wide and 54.75" deep alcove.	§605.3	Remove/relocate partitions to provide a 36" (914 mm) min. wide alcove for a forward approach to object (2010 ADA Fig. 305.7.1). Per 2010 ADA section 213.3 urinals are only required to comply with section 605 where more than one urinal is provided.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0104	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Urinal is mounted at 17.75" (451 mm) above the finished floor to top of rim.	§605.2	Lower urinal and mount at 17" (431 mm) max. above the finished floor to top of rim. (2010 ADA Fig. 605.2). Per 2010 ADA section 213.3 urinals are only required to comply with section 605 where more than one urinal is provided.
ACS	0107	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Maneuvering clearance on the pull side of the stall door is 4.5" (114 mm).	§404.2.4	Rework door stall partitions to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0108	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Water closet does not have a rear wall grab bar.	§604.5.2	Install a 36" (914 mm) min. long rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.2).
ACS	0109	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Accessible toilet compartment (stall) is 38.5" (978 mm) wide.	§604.8.1.1	Remove second toilet stall and convert into one accessible standard stall. Rework partitions and fixtures to provide a 60" by 59" (1524 mm by 1498 mm) min. accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1).
ACS	0110	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Water closet is centered at 19" (483 mm) from side wall	§604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0111	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Toilet compartment side wall grab bar is mounted at 53.5" (1359 mm) perpendicular from rear wall to centerline of its outer flange.	§604.8.2.3	Relocate 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and mount at 33" - 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (ADAAG Fig. 604.5.1)
ACS	0112	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Toilet paper tissue dispenser is mounted over the side wall grab bar.	§609.3	Relocate toilet tissue dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0113	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Toilet tissue dispenser is mounted at 37.5" (952 mm) from rear wall to outer leading edge.	\$604.9.6	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 14"-19" (381 mm to 1219 mm) above the finished floor to the dispenser outlet (2010 ADA Fig. 604.7)
ACS	0114	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Toilet seat cover dispenser is mounted beyond reach ranges at 51.5" (1308 mm) above the finished floor.	\$308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0117	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 58.5" (1486 mm) above the finished floor to paper.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0118	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Paper towel dispenser protrudes into walkway, projecting 11" (279 mm) from back wall, and is mounted at 52.75" (1340 mm) above the finished floor to its bottom leading edge.	\$307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0119	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Shower head is a fixed-type unit.	\$607.6	Replace or install additional shower spray unit with a hose 59" (1500 mm) min. long that serves both as a fixed and hand-held unit. Shower spray unit shall have an on/off control with a non-positive shut-off and deliver water at 120 F maximum.
ACS	0120	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Transfer shower controls are mounted on the wrong wall.	\$608.5.1	Mount shower controls on the side wall opposite to the seat, between 38" (965 mm) min. - 48" (1220 mm) max. above the finished floor to the highest operable part and at 15" (380 mm) from centerline to the edge of shower.
ACS	0121	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Transfer shower grab bar is mounted at a point of 39" (991 mm) from the control wall	\$608.3.1	Install grab bars across the control wall and back wall to a point 18" (457 mm) from the control wall; and mount between 33" and 36" (838 mm- 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig.608.3.1).
ACS	0122	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	The back of the transfer seat is 3" (75mm) from back wall.	\$610.3.2	Provide an L-shaped seat that extends up to 3" (75 mm) max. from the shower compartment entry, that is recessed 2.5" (63 mm) max. from the seat wall and 1.5" (38 mm) max. from the rear edge of the L-portion of the seat (2010 ADA Fig. 610.3.2).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0123	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Transfer shower stall dimensions are 49.75" by 60.25" (1263 by 1530 mm).	§608.2.1	Reconfigure room's fixtures and/or offset partitions to provide a 36" by 36" (914 mm by 914 mm) shower stall with the required 36" by 48" (914 mm by 1219 mm) min. clear floor space (2010 ADA Fig. 608.2.1).
ACS	0125	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Water closet does not have a rear wall grab bar.	§604.5.2	Install a 36" (914 mm) min. long rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.2).
ACS	0126	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Accessible toilet compartment (stall) is 44" (1118 mm) wide.	§604.8.1.1	Remove second toilet stall and convert into one accessible standard stall. Rework partitions and fixtures to provide a 60" by 59" (1524 mm by 1498 mm) min. accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1).
ACS	0127	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Toilet tissue dispenser is mounted over the side wall grab bar.	§609.3	Relocate toilet tissue dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified.
ACS	0128	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Toilet seat cover dispenser is mounted beyond reach ranges at 50.5" (1283 mm) above the finished floor.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0131	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0022	1st	COM SPC	Drinking fountains next to Women's Accessible Restroom	Drinking fountain water flow is less than 4" (102 mm) high.	§602.6	Adjust to provide a flow of water at least 4" (101 mm) high so as to allow the insertion of a cup under it.
ACS	0135	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Call button is mounted beyond required reach allowed for approach provided and is mounted at 49.75" (1264 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the
ACS	0136	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 50.75" (1289 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the
ACS	0138	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Shelf is mounted beyond required reach allowed for approach provided and is mounted at 48.75" (1238 mm) above the finished floor.	§603.4	Lower or install shelf between 40"- 48" (1016 mm -1219 mm) max. above the finished floor for forward approach to object. Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0139	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Writing board is mounted beyond required reach allowed for approach provided and is mounted at 51" (1295 mm) above the finished floor.	§308.2.1	We recommend providing half the writing surface at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0140	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Bench encroaches over writing board clear floor space.	§305.3	Relocate bench to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (ADAAG Figs. 305.3-305.5).
ACS	0141	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Billiard sticks are mounted beyond required reach allowed for approach provided and is mounted at 68" (1727 mm) above the finished floor to the highest operable part	§308.2.1	Lower or install billiard sticks at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0142	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Wall cabinets over the work surface are mounted at 52.5" (1334 mm) above the finished floor to the bottom shelf.	§804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0143	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 51" (1295 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0144	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	TV provided does not have the closed caption feature turned on	§36.303(e)	Implement a policy to have the closed caption feature on during business hours.
ACS	0145	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Game tables have a non-compliant 16.5" (419 mm) knee projection.	§902.2	Provide accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b)).
ACS	0146	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0024	1st	COM SPC	Corridor Next to Game Room Number 8	Planters protrudes into walkway, projecting 14" (356 mm) from back wall, and is mounted at 72" (1829 mm) above the finished floor to its bottom leading edge.	§307.2a	Relocate planters or mount at or above 80" (2032 mm) above the finished floor to its bottom leading edge.
ACS	0147	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Corridor Next to Game Room Number 8	Emergency pull station is mounted at 60.25" (1530 mm) above the finished floor to highest operable part.	§308.2.1	Lower or install emergency pull station at 48" (1219 mm) max. above the finished floor to highest operable part (2010 ADA Fig. 308.2.1).
ACS	0148	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0025	1st	COM SPC	Ceramics Room Number 7	Planter protrudes into walkway, projecting 14" (356 mm) from back wall, and is mounted at 66.5" (1689 mm) above the finished floor to its bottom leading edge.	§307.2a	Relocate planters or mount at or above 80" (2032 mm) above the finished floor to its bottom leading edge.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0151	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Ceramics Room Number 7	Closet Shelf is mounted beyond required reach range for approach provided and is mounted at 49" (1245 mm) above the finished floor.	§811.3	Lower or install accessible shelf at 48" (1219 mm) max. above the finished floor for forward or side approach to object 10" (254 mm) max. deep (ADAAG Fig. 308.3.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0152	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Ceramics Room Number 7	Sink has unwrapped bottom pipes.	§804.4	Cover (insulate) sink bottom supply and drain pipes.
ACS	0153	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Ceramics Room Number 7	Sink does not have the required clear floor space.	§804.4	Remove wooden piece to provide a 30" by 48" (762 mm by 1219 mm) min. sink clear floor space and <u>ensure finish floor extends under cabinet.</u>
ACS	0154	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Ceramics Room Number 7	Wall cabinets over the work surface are mounted at 52.5" (1334 mm) above the finished floor to the bottom shelf.	§804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0157	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Travel office Room Number 6	Planter protrudes into walkway, projecting 14" (356 mm) from back wall, and is mounted at 65" (1651 mm) above the finished floor to its bottom leading edge.	§307.2a	Remove or relocate planter and mount at or above 80" (2032 mm) above the finished floor to its bottom leading edge (2010 ADA Fig. 307.2).
ACS	0160	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Travel office Room Number 6	Reception counter is mounted at 39.25" (997 mm) above the finished floor.	§904.4.1	Provide an alternative counter or rework reception counter to provide a portion that is 36" (914 mm) min. long, mounted at 36" (914 mm) max. above the finished floor to the top (For a parallel approach to counter). An alternative is to provide a clipboard.
ACS	0161	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Travel office Room Number 6	Tables has a non-compliant clear floor space due to table base.	§902.2	Replace tables to provide accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0168	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Multipurpose Room Number 4	Wall cabinets over the work surface are mounted at 52.25" (1327 mm) above the finished floor to the bottom shelf.	§804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0169	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Multipurpose Room Number 4	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 59.75" (1518 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0171	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Healthy Cooking and Sewing Room Number 3	Tables have a non-compliant knee clearance that is 29.25" (743 mm) wide.	§902.2	Provide seating with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance that is 30" (762 mm) min. wide and has a 17" (430 mm) horizontal projection.
ACS	0172	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Healthy Cooking and Sewing Room Number 3	Kitchen sink counter does not have the required knee clearance.	§804.4	Rework sink to provide a 27" (685 mm) min. knee clearance above the finished floor to bottom leading edge of fixture at an 8" (203 mm) min. horizontal projection (2010 ADA Fig. 306.3)
ACS	0173	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Healthy Cooking and Sewing Room Number 3	Sink has unwrapped bottom pipes.	§804.4	Cover (insulate) sink bottom supply and drain pipes.
ACS	0174	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Healthy Cooking and Sewing Room Number 3	Sink is mounted at 35.5" (902 mm) above the finished floor to top of rim.	§804.4	Relocate and/or mount sink at 34" (863 mm) max. above the finished floor to top of rim.
ACS	0175	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Healthy Cooking and Sewing Room Number 3	Sink knob-type faucet requires pinching and tight grasping to operate.	§804.4	Replace or retrofit sink controls with paddle-operated, push-type or electronically-controlled mechanism.
ACS	0176	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Healthy Cooking and Sewing Room Number 3	Wall cabinets over the work surface are mounted at 55" (1397 mm) above the finished floor to the bottom shelf.	§804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0177	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Healthy Cooking and Sewing Room Number 3	Soap dispenser is mounted beyond required reach allowed for approach provided and is mounted at 47" (1194 mm) above the finished floor	§308.2.1	Install soap dispenser at 44" (1219 mm) max. above the finished floor, over a 20"- 25" (510 mm - 1120 mm) max. obstruction, and at 15" (381 mm) min. above the finished floor to the centerline for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0179	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Computer Room Number 2	Trash bins encroaches over thermostat and call button clear floor space.	§305.3	Relocate trash bin to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (ADAAG Figs. 305.3-305.5).
ACS	0182	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Computer Room Number 2	Computers do not appear to have accessible software.	§508	Computers do not appear to have accessible software: Title II of the ADA requires that programs, services and activities offered by public agencies be accessible to persons with disabilities. Section 508 of the Rehabilitation Act of 1973 provides guidelines for developing, procuring, maintaining, or using electronic and information technology. Per Section 508 ensure computer provides accessible hardware/software

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0183	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Computer Room Number 2	Shelf is mounted beyond required reach allowed for approach provided and is mounted at 48.75" (1238 mm) above the finished floor.	\$603.4	Lower or install shelf between 40"- 48" (1016 mm -1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0185	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Number 1	Tables have a non-compliant 26.75" (679 mm) knee clearance .	\$902.2	Provide seating with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance, that is 30" (762 mm) min. wide and has a 17" (430 mm) horizontal projection.
ACS	0186	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Number 1	Sink has unwrapped bottom pipes.	\$804.4	Cover (insulate) sink bottom supply and drain pipes.
ACS	0187	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Number 1	Wall cabinets over the work surface are mounted at 52.75" (1340 mm) above the finished floor to the bottom shelf.	\$804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0188	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Number 1	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 54" (1372 mm) above the finished floor to paper.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0190	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Number 1	Table encroaches over call button clear floor space.	\$305.3	Relocate table to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (ADAAG Figs. 305.3-305.5).
ACS	0191	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Number 1	Call button is mounted beyond required reach allowed for approach provided and is mounted at 50" (1270 mm) above the finished floor.	\$308.2.1	Lower or install call button at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0197	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0035	1st	COM SPC	Corridor adjacent to Manager's Office	AED protrudes into walkway, projecting 7.25" (184 mm) from back wall, and is mounted at 30.25" (768 mm) above the finished floor to its bottom leading edge.	\$307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0200	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Hand dryer protrudes into walkway, projecting 7.5" (190 mm) from back wall, and is mounted at 48" (1219 mm) above the finished floor to its bottom leading edge.	\$307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge or place a cane detectable element underneath (2010 ADA Fig. 307.2).
ACS	0201	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Hand dryer is mounted beyond required reach allowed for approach provided and is mounted at 49" (1245 mm) above the finished floor to operable part.	\$308.2.1	Lower or install hand dryer at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0202	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 53.5" (1359 mm) above the finished floor to paper.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0203	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Paper towel protrudes into walkway, projecting 10" (254 mm) from back wall, and is mounted at 48" (1219 mm) above the finished floor to its bottom leading edge.	\$307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0204	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Urinal is mounted at 18" (457 mm) above the finished floor to top of rim.	\$605.2	Lower urinal and mount at 17" (431 mm) max. above the finished floor to top of rim. (2010 ADA Fig. 605.2)
ACS	0207	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 62.5" (1588 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0208	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Water closet is centered at 21.5" (546 mm) from side wall.	\$604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0210	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Toilet tissue dispenser is mounted at 16.75" (425 mm) in front of the water closet to the centerline of the dispenser.	\$604.7	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet.
ACS	0211	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0037	1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Door has a non-compliant opening force of 8 lbf.	\$404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	0212	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Hand dryer protrudes into walkway, projecting 7.5" (190 mm) from back wall, and is mounted at 48" (1219 mm) above the finished floor to its bottom leading edge.	\$307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0213	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Paper towel dispenser protrudes into walkway, projecting 8.5" (216 mm) from back wall, and is mounted at 47" (1194 mm) above the finished floor to its bottom leading edge.	\$307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0214	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Lavatory is mounted at 34.5" (876 mm) above the finished floor to top of rim.	\$606.3	Relocate lavatory at 34" (863 mm) max. above the finished floor to front end of rim or counter.
ACS	0216	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 62" (1575 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object.
ACS	0217	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Water closet side wall grab bar is mounted at 40" (1016 mm) perpendicular from rear wall to centerline of its outer flange due to a chase.	\$604.5.1	Readily achievable barrier removal has been conducted to the maximum extent feasible (ADAAG Fig. 604.5.1).
ACS	0218	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Toilet tissue and toilet seat cover dispensers are mounted over the side wall grab bar.	\$609.3	Relocate toilet tissue and toilet seat cover dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3). Per 36.304(d)(2)(j) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0219	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Water closet is centered at 22.5" (572 mm) from side wall.	\$604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0221	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 63.5" (1613 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object
ACS	0222	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Toilet tissue dispenser is mounted at 10.5" (267 mm) in front of the water closet to the centerline of the dispenser.	\$604.7	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet.
ACS	0223	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0038	1st	COM SPC	Dining Area	Tables have a non-compliant 26.75" (679 mm) knee clearance .	\$902.2	Replace tables to provide 5% accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b)).
ACS	0224	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Dining Area	TV provided does not have the closed caption feature turned on	\$36.303(e)	TV provided does not have the closed caption feature turned on. Implement a policy to have the closed caption feature on during business hours.
ACS	0228	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Dining Area	Tables have a non-compliant 26.75" (679 mm) knee clearance .	\$902.2	Provide accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b)).
ACS	0229	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0039	1st	COM SPC	Water fountains next to Dining Area	Wall/post mounted drinking fountain has a 12.75" (324 mm) knee clearance.	\$602.1	Relocate/rework fountain to provide a 27" (685 mm) min. knee clearance above the finished floor, 30" (762 mm) min. wide and 25" (635 mm) max. deep (2010 ADA Fig. 306.3). As an alternative, provide cups to be used as a side approach.
ACS	0232	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 54.5" (1384 mm) above the finished floor to paper.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0233	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Hand dryer is mounted beyond required reach allowed for approach provided and is mounted at 53" (1346 mm) above the finished floor.	\$308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(j) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0234	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Lavatory has partially unwrapped bottom sink pipes.	\$606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0235	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Urinal is mounted in a 34.75" wide and 36" deep alcove.	§605.3	Remove/relocate partitions to provide a 36" (914 mm) min. wide alcove for a forward approach to object. Alternative is to replace partition to be 24" (610 mm) deep max (2010 ADA Fig. 305.7.1). Per 2010 ADA section 213.3 urinals are only required to comply with section 605 where more than one urinal is provided.
ACS	0236	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Urinal is mounted at 24.5" (622 mm) above the finished floor to top of rim.	§605.2	Lower urinal and mount at 17" (431 mm) max. above the finished floor to top of rim. (2010 ADA Fig. 605.2). Per 2010 ADA section 213.3 urinals are only required to comply with section 605 where more than one urinal is provided.
ACS	0239	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 56.5" (1435 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0240	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Maneuvering clearance on the pull side of the door is 7" (178 mm).	§404.2.4	Rework door side partition to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0241	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Accessible toilet compartment (stall) is 35.5" (899 mm) wide.	§604.8.1.1	Remove second toilet stall and convert into one accessible standard stall. Rework partitions and fixtures to provide a 60" by 59" (1524 mm by 1498 mm) min. accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1).
ACS	0242	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Water closet does not have a rear wall grab bar.	§604.5.2	Install a 36" (914 mm) min. long rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.2).
ACS	0243	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Water closet side wall grab bar is mounted at 53.5" (1359 mm) perpendicular from rear wall to centerline of its outer flange.	§604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (ADAAG Fig. 604.5.1)
ACS	0245	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Toilet tissue dispenser is mounted over the side wall grab bar.	§609.3	Relocate toilet tissue dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3).
ACS	0249	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Lavatory has unwrapped bottom sink pipes.	§606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0250	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Lavatory is mounted at 35" (889 mm) above the finished floor to top of rim.	§606.3	Relocate lavatory at 34" (863 mm) max. above the finished floor to front end of rim or counter.
ACS	0252	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Hand dryer is mounted beyond required reach allowed for approach provided and is mounted at 52" (1321 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object. (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0253	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 53" (1346 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0254	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Paper towel dispenser protrudes into walkway, projecting 11" (279 mm) from back wall, and is mounted at 47.75" (1213 mm) above the finished floor to its bottom leading edge.	§307.2r	Relocate or recess so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0256	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 57" (1448 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0257	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Accessible toilet compartment (stall) is 36" (914 mm) wide.	§604.8.1.1	Rework partitions and/or fixtures to provide a 60" by 59" (1524 mm by 1498 mm) min. accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1).
ACS	0258	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Water closet side wall grab bar is mounted at 53.5" (1359 mm) perpendicular from rear wall to centerline of its outer flange.	§604.5.1	Relocate 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (ADAAG Fig. 604.5.1)
ACS	0259	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Toilet tissue dispenser is mounted over the side wall grab bar.	§609.3	Relocate toilet tissue dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0260	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Toilet seat cover dispenser is mounted on top of the side wall grab bar.	§609.3	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar . If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)
ACS	0261	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331	0042	1st	COM SPC	Corridor next to William Bridge Room	Fire extinguisher latch is mounted beyond required reach allowed for approach provided and is mounted at 62" (1575 mm) above the finished floor.	§308.2.1	Lower or install fire extinguisher latch at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0265	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Across from William Bridge Room	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 49.5" (1257 mm) above the finished floor.	§308.3	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0266	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Across from William Bridge Room	Clothes rod is mounted beyond required reach allowed for approach provided and is mounted at 57.5" (1460 mm) above the finished floor.	§308.2.1	Lower or install accessible clothes rod at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0267	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Across from William Bridge Room	Closet Shelf is mounted beyond required reach range for approach provided and is mounted at 59.75" (1518 mm) above the finished floor.	§811.3	Lower or install accessible shelf at 48" (1219 mm) max. above the finished floor for forward or side approach to object 10" (254 mm) max. deep (ADAAG Fig. 308.3.1).
ACS	0268	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Across from William Bridge Room	Fan control is mounted beyond required reach allowed for approach provided and is mounted at 76.5" (1943 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0269	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Room Across from William Bridge Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 71" (1803 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0273	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Clothes rod is mounted beyond required reach allowed for approach provided and is mounted at 57.75" (1467 mm) above the finished floor.	§308.2.1	Lower or install accessible clothes rod at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0274	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Fan controls is mounted beyond required reach allowed for approach provided and is mounted at 76.5" (1943 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0275	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 68" (1727 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0276	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Sink counter does not have the required knee clearance.	§804.3.1	Rework sink to provide a 27" (685 mm) min. knee clearance above the finished floor to bottom leading edge of fixture at an 8" (203 mm) min. horizontal projection (2010 ADA Fig. 306.3)
ACS	0277	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Sink has unwrapped bottom pipes.	§804.4	Cover (insulate) sink bottom supply and drain pipes.
ACS	0278	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Sink knob-type faucet requires pinching and tight grasping to operate.	§804.4	Replace or retrofit sink controls with paddle-operated, push-type or electronically-controlled mechanism.
ACS	0279	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Soap dispenser is mounted beyond required reach allowed for approach provided and is mounted at 44.25" (1124 mm) above the finished floor	§308.2.1	Lower or install soap dispenser at 44" (1118 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). <i>This dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.</i>
ACS	0280	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	William "Bill" Marshall Bridge Room	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 47.5" (1206 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 44" (1219 mm) max. above the finished floor, over a 20"- 25" (510 mm - 1120 mm) max. obstruction for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0284	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Music Room	Table work surface is mounted at 34.75" (883 mm) above the finished floor to the top.	§902.3	Rework/replace tables to provide the top of the dining or work surface, mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground.
ACS	0285	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Music Room	Lectern is mounted at 41" (1041 mm) above the finished floor to the top.	§902.3	Rework/replace lectern to provide the top of the work surface, mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground.
ACS	0286	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Music Room	Sink counter does not have the required knee clearance.	§804.3.1	Rework sink to provide a 27" (685 mm) min. knee clearance above the finished floor to bottom leading edge of fixture at an 8" (203 mm) min. horizontal projection (2010 ADA Fig. 306.3).
ACS	0287	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Music Room	Sink has unwrapped bottom pipes.	§804.4	Cover (insulate) sink bottom supply and drain pipes.
ACS	0288	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Music Room	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 53" (1346 mm) above the finished floor to paper.	§308.2.1	Lower or install paper towel dispenser at 44" (1219 mm) max. above the finished floor, over a 20"- 25" (510 mm - 1120 mm) max. obstruction, for forward approach to object (2010 ADA Fig. 308.2.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0289	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Music Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 70" (1778 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0290	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Music Room	Fan control is mounted beyond required reach allowed for approach provided and is mounted at 77" (1956 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0294	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Waiting Room	Ensure TV provides closed caption during business hours.	§36.303(e)	Replace existing TV set if needed with a closed caption compatible unit or install a caption decoder system.
ACS	0309	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		Grade	COM SPC	Proposed Location for Accessible Parking Spaces in Front of Accessible Entrance	An alternative proposed correction is to relocate the 3 accessible parking spaces to this location.	§403.3	Accessible route has a non-compliant cross slopes of up to 4.2 %. And there are surface slope issues at parking area.
ACS	*0134	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Door has a non-compliant opening force.	§404.2.9	Adjust or replace door closer, maintain door hinges to provide an opening force not to exceed 5 lbf.
ACS	*0137	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Game Room Number 8	Clothes rod is mounted beyond required reach allowed for approach provided and is mounted at 50.75" (1289 mm) above the finished floor.	§308.2.1	Lower or install accessible clothes rod at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	*0244	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Toilet tissue dispenser is mounted at 11.5" (292 mm) in front of the water closet to the centerline of the dispenser.	§604.7	Relocate toilet tissue dispenser to water closet side wall at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet.
ACS	0105	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provide pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0106	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0124	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provide pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0130	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Water closet is centered at 21.75" (552 mm) from side wall.	§604	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0205	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provide pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0206	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom adjacent to Manager's Office	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0215	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provide pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0220	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom adjacent to Manager's Office	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provide pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0237	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provide pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0238	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Men's Accessible Restroom	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0255	Senior Services	Quality Living Services	4001 Danforth Rd SW Atlanta, GA 30331		1st	COM SPC	Women's Accessible Restroom	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provide pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0002	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Main Entrance	Mat is not securely attached to the floor.	§305.3	Provide a securely attached mat with a leveled loop or level cut pile, with texture height that is 0.5" (13 mm) max. and has a firm cushion pad or backing (2010 ADA Fig. 302.2).
ACS	0008	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Breakfast Area (Pack Room)	Exit door mat is not securely attached to the floor.	§305.3	Provide a securely attached mat with a leveled loop or level cut pile, with texture height that is 0.5" (13 mm) max. and has a firm cushion pad or backing (2010 ADA Fig. 302.2).
ACS	0001	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0001	1st	COM SPC	Main Entrance	Chairs encroach over door opener clear floor space.	§305.3	Relocate chairs to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0007	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Breakfast Area (Pack Room)	Exit door signage does not have Braille or raised characters and is mounted on the hinge side of door.	§216.4	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0009	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0003	1st	COM SPC	Women's Restroom by Kitchen	Permanent room identifying signage is mounted on the door leaf.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0010	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Characters and Braille are located in the pictogram field.	\$703.6.1	Rework / replace signage to provide a minimum pictogram field border height of 6" (152 mm) where characters and Braille are not within the pictogram field (2010 ADA Fig. 703.6.1)
ACS	0011	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Doorway opening has a clear width of 21.25" (540 mm).	\$404.2.3	Rework doorway (partition) to provide the required 32" (812 mm) min. clear door or entryway width.
ACS	0012	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Maneuvering clearance on the pull side of the door is 6" (152 mm).	\$404.2.4	Rework cabinet to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0013	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Lavatory does not provide the required knee clearance.	\$606.2.2	Rework lavatory to provide the required 27" (685 mm) min. knee clearance above the finished floor to bottom leading edge of fixture at an 8" (203 mm) min. horizontal projection (2010 ADA Fig. 306.3).
ACS	0014	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Lavatory has unwrapped bottom sink pipes.	\$606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0015	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Stall doorway opening has a clear width of 22.25" (565 mm).	\$404.2.3	Rework stall doorway (partitions) to provide the required 32" (812 mm) min. clear door or entryway width (2010 ADA Fig. 404.2.3).
ACS	0016	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	\$604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0017	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 68" (1727 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0018	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Toilet seat cover dispenser is mounted behind the water closet.	\$308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)
ACS	0019	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Restroom by Kitchen	Accessible toilet compartment (stall) is 34.5" by 55.75" (876 by 1416 mm) wide.	\$604.8.1.1	Rework partitions and/or fixtures to provide a 60" by 59" (1524 mm by 1498 mm) min. accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1). Alternative is to post sign indicating location of accessible restroom.
ACS	0020	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0004	1st	COM SPC	Women's Accessible Restroom by Fitness Room	Permanent room identifying signage is mounted on the hinge side of the door.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0033	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Maneuvering clearance on the pull side of the door is 12.5" (318 mm).	\$404.2.4	Install automatic door opener to comply with requirements for a 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0035	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0006	1st	COM SPC	Men's Accessible Restroom	Permanent room identifying signage is mounted at 61" (1549 mm) to the baseline of the highest tactile character.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0036	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Maneuvering clearance on the pull side of the door is 5.25" (133 mm).	\$404.2.4	Install automatic door opener to comply with requirements for a 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0052	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Art Room	Furniture encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate furniture to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0076	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0011	2nd	COM SPC	Painting Room	Permanent room identifying signage does not have Braille or raised characters and is mounted on the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0077	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0012	2nd	COM SPC	Painting Room 2	Permanent room identifying signage does not have Braille or raised characters and is mounted on the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0078	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Painting Room 2	Table encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate table to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0083	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0014	2nd	COM SPC	Office	Permanent room identifying signage does not have Braille or raised characters and is mounted on the door leaf.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0084	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Office	The computers do not appear to provide accessible software.	\$508	Title II of the ADA requires that programs, services and activities offered by public agencies be accessible to persons with disabilities. Section 508 of the Rehabilitation Act of 1973 provides guidelines for developing, procuring, maintaining, or using electronic and information technology. Per Section 508 ensure computer provides accessible hardware/software
ACS	0090	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0017	Grade	COM SPC	Passenger Loading Zone	Passenger loading zone does not have signage displaying the international symbol of accessibility.	\$216.2	Provide a sign indicating passenger loading zone, displaying the International symbol of accessibility.
ACS	0091	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Passenger Loading Zone	Passenger loading zone access aisle is not striped or marked.	\$503.3.2	Provide a 60" (1524 mm) min. wide access aisle serving a 20 ft. (6096 mm) min. long vehicle pull up space with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 503.3).
ACS	0092	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Curb Ramp from Passenger Loading Zone to Entrance	Curb ramp has a 10.9 % non-compliant running slope.	\$406	Rework curb ramp to provide a running slope not to exceed 8.33%
ACS	0093	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0018	Grade	COM SPC	Curb Ramp from Passenger Loading Zone to Entrance	Curb ramp has a 26.3 % slope on the flare side.	\$406.3	Rework curb ramp to provide a 10% max. slope on the flare sides (For curb ramps with a 36" (915 mm) top landing (2010 ADA Fig. 406.3).
ACS	0094	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Curb Ramp from Passenger Loading Zone to Entrance	Curb ramp has a 14.2 % slope on the flare side.	\$406.3	Rework curb ramp to provide a 10% max. slope on the flare sides (For curb ramps with a 36" (915 mm) top landing (2010 ADA Fig. 406.3).
ACS	0095	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0019	Grade	COM SPC	Two Accessible Parking Spaces on East Side of Facility	Left van-accessible parking space is not clearly outlined or needs re-striping.	\$502.2	Restripe to provide a van-accessible parking space 96" (2438 mm) min. wide and a 96" (2438 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (When access aisle is 96" (2438) wide) (2010 ADA Figs. 502.2).
ACS	0098	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Two Accessible Parking Spaces on East Side of Facility	Van access aisle is faded	\$502.3	Restripe to provide a 96" (2438 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (When parking space is 96" (2438 mm) wide)
ACS	0099	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Two Accessible Parking Spaces on East Side of Facility	Accessible parking space on right has non-compliant surface slopes of up to 3.0%	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	0100	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0020	Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	Right van-accessible parking space is not clearly outlined or needs re-striping.	\$502.2	Restripe to provide a van-accessible parking space 96" (2438 mm) min. wide and a 96" (2438 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (When access aisle is 96" (2438) wide) (2010 ADA Figs. 502.2).
ACS	0102	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	First van-accessible parking space from left to right is faded.	\$502.2	Restripe to provide a van-accessible parking space 96" (2438 mm) min. wide and a 96" (2438 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (When access aisle is 96" (2438) wide) (2010 ADA Figs. 502.2).
ACS	0104	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	First van access aisle from left to right is faded.	\$502.3	Restripe to provide a van-accessible parking space 96" (2438 mm) min. wide and a 96" (2438 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (When parking space is 96" (2438 mm) wide)
ACS	0106	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	Second accessible parking space from left to right is faded.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0108	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	Third accessible parking space from left to right is faded.	\$502.3.1	Restripe to provide an accessible parking space 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	0110	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	Second access aisle from left to right is faded.	\$502.3.1	Restripe area to provide an accessible parking space that has a 60" (1524 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 502.3).
ACS	0111	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0021	1st	COM SPC	Accessible Route From Accessible Parking Spaces on West Side Leading to Main Entrance	The surface of the accessible route leading to main entrance has loose material.	\$302.1	Rework and clean sidewalk to provide a stable, firm, and slip-resistant floor surface.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0112	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0022	1st	COM SPC	Accessible Route From Accessible Parking Spaces on West Side Leading to Main Entrance	Curb ramp has a 12 % non-compliant running slope.	\$406	Rework curb ramp to provide a running slope not to exceed 8.33%
ACS	0113	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Accessible Route From Accessible Parking Spaces on West Side Leading to Main Entrance	Curb ramp has a 28 % slope on the left flare side.	\$406.4	Rework curb ramp to provide an 8.33% max slope on the flare sides.
ACS	0114	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Accessible Route From Accessible Parking Spaces on West Side Leading to Main Entrance	Curb ramp has a 11.2 % slope on the right flare side.	\$406.4	Rework curb ramp to provide an 8.33% max slope on the flare sides.
ACS	0115	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Accessible Route From Accessible Parking Spaces on West Side Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.9 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0116	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Accessible Route From Accessible Parking Spaces on West Side Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.6 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0117	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Accessible Route From Accessible Parking Spaces on West Side Leading to Main Entrance	Accessible route has a non-compliant cross slope of 2.6 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0118	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Accessible Route From Accessible Parking Spaces on West Side Leading to Main Entrance	Accessible route has a non-compliant cross slope of 2.4 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0119	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Accessible Route From Accessible Parking Spaces on West Side Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	*0096	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Two Accessible Parking Spaces on East Side of Facility	Accessible parking space on left has non-compliant surface slopes of up to 2.9%	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0097	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Two Accessible Parking Spaces on East Side of Facility	Access aisle has non-compliant running slope of up to 5.3%	\$502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	*0101	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	First van-accessible parking space from left to right has up to 6.5 % non-compliant running slopes.	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0103	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	First access aisle from left to right has a 6.9 % non-compliant running slope.	\$502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	*0105	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	Second accessible parking space from left to right has up to 7 % non-compliant running slopes.	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0107	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	Third accessible parking space from left to right has up to 5.9 % non-compliant running slopes.	\$504.2	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0109	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		Grade	COM SPC	Three Accessible Parking Spaces on West Side of Facility	Second access aisle from left to right has up to 4.8 % non-compliant running slopes.	\$502.4	Rework or repave to provide an access aisle with running slope not exceeding 2% in all directions.
ACS	0003	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Lobby	Chairs encroach over light switch and fire extinguisher clear floor space.	\$305.3	Remove chairs to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space light switch and fire extinguisher (201 ADA Figs. 305.3-305.5).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0004	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Multipurpose Room	Tables have a non-compliant 29.25" (743 mm) wide knee clearance.	§902.2	Replace tables to provide 5% accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0005	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0002	1st	COM SPC	Multipurpose Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 66.25" (1683 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0006	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Breakfast Area (Pack Room)	Tables have a non-compliant 29.75" (749 mm) knee clearance and non-compliant clear floor space provided.	§902.2	Replace tables to provide 5% accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0021	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Lavatory has partially unwrapped bottom sink pipes.	§606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0022	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Lavatory mirror is mounted at 47.5" (1206 mm) above the finished floor to bottom edge of its reflecting surface.	§603.3	Lower lavatory mirror to 40" (1016 mm) max. above the finished floor to bottom edge of its reflecting surface.
ACS	0023	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Soap dispenser is mounted at 47.25" (1200 mm) above finished floor over an obstruction (sink counter).	§603.3	Lower or install soap dispenser at 44" (1219 mm) max. above the finished floor to the highest operable part, over a 20" - 25" (510 mm - 1120 mm) max. obstruction for a forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0026	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 63.25" (1607 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0027	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Toilet seat cover dispenser is mounted beyond reach ranges and is mounted behind the water closet.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0028	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Water closet side wall grab bar is mounted at 48.5" (1232 mm) perpendicular from rear wall to centerline of its outer flange.	§604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. (2010 ADA Fig. 604.5.1)
ACS	0029	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Water closet is centered at 18.25" (464 mm) from side wall.	§604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2). For a facility that pre-dates the enactment of the ADA this dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.
ACS	0030	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Water closet has the rear wall grab bar mounted at 10" (254 mm) perpendicular from side wall to centerline of water closet.	§604.5.2	Install a 36" (914 mm) min. long rear wall grab bar that extends 24" (610 mm) min. from water closet centerline to the outer flange (on open side) of the grab bar and 12" (305 mm) min. from the water closet centerline to the inner flange (on wall side) of grab bar, mount between 33" and 36" (838 mm - 914 mm) above the floor to top of the gripping surface (2010 ADA Fig 604.5.2)
ACS	0031	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Toilet tissue dispenser is mounted 6.5" (165 mm) over the side wall grab bar.	§609.3	Relocate item to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0032	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Accessible toilet compartment (stall) is 59.75" (1518 mm) wide.	§604.8.1.1	Rework partitions and/or fixtures to provide a 60" wide by 59" long (1524 mm by 1498 mm) min. accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1). For a facility that pre-dates the enactment of the ADA this dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.
ACS	0034	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0005	1st	COM SPC	Drinking Fountain in Front of Women's Accessible Restroom	Wall/post mounted drinking fountain has a 26.75" (679 mm) knee clearance.	§602.1	Relocate/rework fountain to provide a 27" (685 mm) min. knee clearance above the finished floor, 30" (762 mm) min. wide and 25" (635 mm) max. deep (2010 ADA Fig. 306.3).
ACS	0037	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Lavatory has partially unwrapped bottom sink pipes.	§606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0038	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Lavatory mirror is mounted at 47.25" (1200 mm) above the finished floor to bottom edge of its reflecting surface.	\$603.3	Lower lavatory mirror to 40" (1016 mm) max. above the finished floor to bottom edge of its reflecting surface.
ACS	0039	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Soap dispenser is mounted at 47" (1193 mm) above finished floor over an obstruction (sink counter).	\$603.3	Lower or install soap dispenser at 44" (1219 mm) max. above the finished floor to the highest operable part, over a 20" - 25" (510 mm - 1120 mm) max. obstruction for a forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0042	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 58.5" (1486 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0043	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Water closet side wall grab bar is mounted at 49" (1245 mm) perpendicular from rear wall to centerline of its outer flange.	\$604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33" - 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. (2010 ADA Fig. 604.5.1)
ACS	0044	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Toilet seat cover dispenser is mounted behind the water closet.	\$308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). <i>If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar. If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3).</i>
ACS	0045	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Toilet tissue dispenser is mounted 8" (203 mm) over the side wall grab bar.	\$609.3	Relocate toilet tissue dispenser to provide a clear space between the side wall grab bar and projecting objects above of 12" (305 mm) min. (2010 ADA Fig. 609.3). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0046	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Water closet flush control is toward the wall side.	\$604.6	Replace water closet flush control toward the open side or install an electronically controlled mechanism.
ACS	0047	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Water closet is centered at 19.25" (489 mm) from side wall.	\$604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0048	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Accessible toilet compartment (stall) is 59.25" (1505 mm) wide.	\$604.8.1.1	Relocate stall partition to provide a 60" by 59" (1524 mm by 1498 mm) min. accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.1).
ACS	0049	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0007	2nd	COM SPC	Library	Books are mounted beyond required reach allowed for approach provided.	\$308.3.1	As best practice, implement a policy to provide assistance retrieving books out of reach range and post signage indicating that "assistance is available upon request"
ACS	0050	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0008	2nd	COM SPC	Art Room	Desk has a non-compliant 26.5" (673 mm) knee clearance.	\$902.2	Provide desk with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance above the finished floor and a 17" (430 mm) horizontal projection.
ACS	0051	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Art Room	Wall cabinets over the work surface are mounted at 53.75" (1365 mm) above the finished floor to the bottom shelf.	\$804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0053	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0009	2nd	COM SPC	Men's Accessible Restroom	Lavatory has partially unwrapped bottom sink pipes.	\$606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0054	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Lavatory knee clearance is 26.75" (679 mm) above the finished floor to bottom leading edge of fixture.	\$606.2.2	Rework lavatory to provide the required 27" (685 mm) min. knee clearance above the finished floor to bottom leading edge of fixture at an 8" (203 mm) min. horizontal projection (2010 ADA Fig. 306.3). <i>For a facility that pre-dates the enactment of the ADA this dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.</i>
ACS	0055	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Lavatory mirror is mounted at 50.25" (1276 mm) above the finished floor to bottom edge of its reflecting surface.	\$603.3	Lower lavatory mirror to 40" (1016 mm) max. above the finished floor to bottom edge of its reflecting surface.
ACS	0056	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Scale encroaches over maneuvering clearance on the pull side of the stall door.	\$404.2.4	Relocate scale to provide the required 42" (1065 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0057	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	\$604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0058	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 57" (1448 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object
ACS	0059	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Accessible toilet compartment (stall) door is not located in partition or side wall farthest from water closet.	\$604.8.1.2	Accessible toilet compartment (stall) door shall be located in the front partition or in the side wall or partition farthest from the water closet.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0060	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Toilet seat cover dispenser is mounted behind the water closet.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). <i>If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar . If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)</i>
ACS	0061	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Water closet flush control is toward the wall side.	§604.6	Rotate water closet flush control toward the open side or install an electronically controlled mechanism.
ACS	0062	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Water closet is centered at 18.5" (470 mm) from side wall.	§604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0063	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Water closet side wall grab bar is mounted at 50" (1270 mm) perpendicular from rear wall to centerline of its outer flange.	§604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. perpendicular from rear wall to centerline of outer flange and at 12" (305 mm) max. perpendicular from rear wall to centerline of inner flange. Mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. (2010 ADA Fig. 604.5.1)
ACS	0064	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Toilet tissue dispenser is mounted 5" (127 mm) over the side wall grab bar.	§609.3	Relocate toilet tissue dispenser to water closet side wall and mount at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet (2010 ADA Fig. 604.7). If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar . If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)
ACS	0065	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Men's Accessible Restroom	Maneuvering clearance on the pull side of the door is 42" (1067 mm).	§404.2.4	Relocate stall partition to provide the required 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1). <i>Alternative proposed correction is to remove stall partitions, install level hardware on door and convert to single user restroom if allowed by local codes and ordinances.</i>
ACS	0066	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0010	2nd	COM SPC	Women's Accessible Restroom	Lavatory has partially unwrapped bottom sink pipes.	§606.5	Cover (insulate) lavatory bottom supply and drain pipes or reconfigure to protect against contact.
ACS	0067	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Women's Accessible Restroom	Lavatory mirror is mounted at 50.5" (1283 mm) above the finished floor to bottom edge of its reflecting surface.	§603.3	Lower lavatory mirror to 40" (1016 mm) max. above the finished floor to bottom edge of its reflecting surface.
ACS	0070	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Women's Accessible Restroom	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 58" (1473 mm) above the finished floor.	§603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0071	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Women's Accessible Restroom	Door is located in front of water closet.	§604.8.1.2	Relocate door 4" (100 mm) max from the side partition farthest from the water closet and provide a 60" by 59" (1524 mm by 1498 mm) min. accessible toilet compartment for a floor mounted water closet (2010 ADA Fig. 604.8.1.2).
ACS	0072	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Women's Accessible Restroom	Toilet seat cover dispenser is mounted behind the water closet.	§308.2.1	Relocate toilet seat cover dispenser and mount between 15" to 48" (380 mm - 1219 mm) above the finished floor for unobstructed forward approach to object (2010 ADA Fig. 308.2.1). <i>If mounted below the side wall grab bar there shall be a clearance of 1.5" (38 mm) below the grab bar . If mounted above the side wall grab bar there shall be a clearance of 12" (305 mm) min. above the grab bar (2010 ADA Fig 609.3)</i>
ACS	0073	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Women's Accessible Restroom	Water closet side wall grab bar is mounted at 52" (1321 mm) perpendicular from rear wall to centerline of its outer flange.	§604.5.1	<i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0074	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Women's Accessible Restroom	Toilet tissue dispenser is mounted over the side wall grab bar.	§609.3	Relocate toilet tissue dispenser to water closet side wall and mount at 7"-9" (177 mm to 228 mm) in front of the water closet to the centerline of the dispenser and 15"-48" (381 mm to 1219 mm) above the finished floor to the dispenser outlet (2010 ADA Fig. 604.7). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0075	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Women's Accessible Restroom	Maneuvering clearance on the pull side of the door is 41.5" (1054 mm).	§404.2.4	Relocate stall partition to provide the required 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1). <i>Alternative proposed correction is to remove stall partitions, install level hardware on door and convert to single user restroom if allowed by local codes and ordinances.</i>

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0079	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Painting Room 2	Desk has a non-compliant 26.5" (673 mm) knee clearance.	§902.2	Provide desk with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance above the finished floor and a 17" (430 mm) horizontal projection.
ACS	0080	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0013	2nd	COM SPC	Hallway Next to Painting Room	Clothes rod is mounted beyond required reach range for approach provided and is mounted at 61" (1549 mm) above the finished floor.	§811.3	Lower or install accessible clothes rod at 48" (1219 mm) max. above the finished floor for forward or side approach to object 10" (254 mm) max. deep (2010 ADA Fig. 308.3.1).
ACS	0081	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Hallway Next to Painting Room	Closet Shelf is mounted beyond required reach range for approach provided and is mounted at 62.25" (1581 mm) above the finished floor.	§811.3	Lower or install accessible shelf at 48" (1219 mm) max. above the finished floor for forward or side approach to object 10" (254 mm) max. deep (2010 ADA Fig. 308.3.1).
ACS	0082	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Hallway Next to Painting Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 59.5" (1511 mm) above the finished floor.	§308.2.1	Lower or install at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0085	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0015	2nd	COM SPC	Game Room	Ensure TV provides closed caption during business hours.	§36.303(e)	Implement a policy to have the closed caption feature on during business hours.
ACS	0086	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Game Room	Tables have a non-compliant 29.25" (743 mm) wide knee clearance.	§902.2	Replace tables to provide accessible seating spaces with the table mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. The table must provide a knee clearance that is at least 27" (685 mm) high, 30" (762 mm) wide and with a horizontal projection that is 17" (432 mm) deep. With it's corresponding 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.5 (a), 306.2 (a)(b) and 306.3 (a)(b))
ACS	0087	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Game Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 62.5" (1588 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install thermostat at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0088	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076			COM SPC	Corridor by Elevator Lobby	Drinking fountain is on the floor.	§602.1	Ensure that when drinking fountain is installed it provides a 27" (685 mm) min. knee clearance above the finished floor, 30" (762 mm) min. wide and 25" (635 mm) max. deep (2010 ADA Fig. 306.3).
ACS	0089	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076	0016	2nd	COM SPC	Elevators	Elevator two-way communication compartment door requires pinching and tight grasping to operate.	§409.4.7.3	Elevator two-way communication compartment door requires pinching and tight grasping to operate.
ACS	0024	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0025	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Women's Accessible Restroom by Fitness Room	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0040	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0041	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		1st	COM SPC	Men's Accessible Restroom	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0068	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Women's Accessible Restroom	Accessible compartment (stall) door does not provide pull handles on both sides of the door near the latch.	§604.8.2.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0069	Senior Services	Roswell Neighborhood Senior Center	1250 Warsaw Rodad Roswell, GA 30076		2nd	COM SPC	Women's Accessible Restroom	Accessible compartment (stall) door does not have a self closing mechanism.	§604.8.2.2	Provide a self closing mechanism on door with an opening force not exceeding 5 lbf.
ACS	0002	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0002	1st	COM SPC	Unisex Restroom by Main Entrance	This restroom is labeled "staff only". There is no signage posted indicating the location of an accessible restroom	§216.6	Post signage indicating location of the restrooms serving the facility. If sign is to be placed overhead it shall have a minimum character height of 3" (76 mm).
ACS	0011	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0005	1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Permanent room identifying signage is mounted on the hinge side of the door.	§703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0049	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Class Room No. 115	Computers do not appear to have accessible software.	§508	Title II of the ADA requires that programs, services and activities offered by public agencies be accessible to persons with disabilities. Section 508 of the Rehabilitation Act of 1973 provides guidelines for developing, procuring, maintaining, or using electronic and information technology. Per Section 508 ensure computer provides accessible hardware/software
ACS	0079	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		Grade	COM SPC	Accessible Parking Spaces	Second access aisle (from left to right) had a car parked on top therefore it was not possible to determine if the slopes were not compliant	§502.4	Rework or repave to provide an access aisle with surface slope not exceeding 2% in all directions.
ACS	0081	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From The Accessible Parking Spaces Leading to Main Entrance	Accessible route has a 0.75" (19 mm) vertical change in level.	§403.4	Rework accessible route to provide a 0.25"-0.5" (6 mm-12 mm) max. change of level, beveled with a slope no greater than 1:2 (2010 ADA Fig. 303.3).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0082	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From The Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.9 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0083	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From The Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.2 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0084	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From The Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 3.5 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0085	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From The Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 4.3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0086	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From The Accessible Parking Spaces Leading to Main Entrance	Accessible route has a non-compliant cross slope of 4.0 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0087	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0019	Grade	COM SPC	Passenger Loading Zone by Main Entrance	Passenger loading zone does not have signage displaying the international symbol of accessibility.	\$503	Provide signage displaying the International symbol of accessibility at passenger loading zone.
ACS	0089	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0020	1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 2.7 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0090	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 2.7 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0091	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 4.5 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0092	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 2.9 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0093	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 2.5 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0094	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 2.5 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0095	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Curb ramp has a 9.8 % non-compliant running slope.	\$406	Rework curb ramp to provide a running slope not to exceed 8.33%
ACS	0096	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Curb ramp surface does not have truncated domes or contrasting color and projects into vehicular traffic lanes.	\$705	We recommend providing truncated domes with a base diameter of 0.9"-1.4" (22 mm-35 mm), a height of 0.2" (35 mm), center-to-center spacing of 1.6"-2.4" (40 mm-61 mm), and base-to-base spacing of 0.65" (17 mm) that contrast visually with adjoining surface.
ACS	0097	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Curb ramp surface does not have truncated domes or contrasting color and projects into vehicular traffic lanes.	\$705	We recommend providing truncated domes with a base diameter of 0.9"-1.4" (22 mm-35 mm), a height of 0.2" (35 mm), center-to-center spacing of 1.6"-2.4" (40 mm-61 mm), and base-to-base spacing of 0.65" (17 mm) that contrast visually with adjoining surface.
ACS	0098	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	The surface of the curb ramp is broken, loose or unstable.	\$406	Rework or repave curb ramp to provide a surface that is stable, firm and slip resistant, with a cross slope not exceeding 8.33%.
ACS	0099	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Curb ramp has 0.5" (13 mm) vertical change of level.	\$406.1	Rework curb ramp to eliminate change of level and provide a slope no greater than 8.33%
ACS	0100	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 7.8 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0101	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 7.2 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0102	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a 2.5" (64 mm) vertical change in level.	\$403.4	Rework accessible route to provide a 0.25"-0.5" (6 mm-12 mm) max. change of level, beveled with a slope no greater than 1:2 or mitigate condition by means of a curb ramp or ramp (2010 ADA Fig. 303.3).
ACS	0103	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 5.3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0105	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a 2.25" (57 mm) vertical change in level.	\$403.4	Rework accessible route to provide a 0.25"-0.5" (6 mm-12 mm) max. change of level, beveled with a slope no greater than 1:2 or mitigate condition by means of a small ramp (2010 ADA Fig. 303.3).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0106	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 3.0 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0107	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 3.0 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0108	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 4.3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0109	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 6.3 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	0110	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant cross slope of 7.8 %.	\$403.3	Rework or repave accessible route to provide a cross slope not exceeding 2%.
ACS	*0075	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0018	Grade	COM SPC	Accessible Parking Spaces	Car are allowed to park over the access aisles serving the accessible parking spaces.	\$502.3.1	Implement policies that prohibit users from parking on the access aisles at all times and provide accessible parking space that are 96" (2438 mm) min. wide and a 60" (15258 mm) min. wide access aisle with a surface slope not exceeding 2% in all directions (2010 ADA Figs. 502.3).
ACS	*0076	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		Grade	COM SPC	Accessible Parking Spaces	First accessible parking space (from left to right) has a non-compliant surface slope of up to 4.3%.	\$502.4	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0077	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		Grade	COM SPC	Accessible Parking Spaces	First access aisle (from left to right) has a non-compliant surface slope of up to 3.8%.	\$502.4	Rework or repave to provide an access aisle with surface slope not exceeding 2% in all directions.
ACS	*0078	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		Grade	COM SPC	Accessible Parking Spaces	Second accessible parking space (from left to right) has a non-compliant surface slope of up to 3.4%.	\$502.4	Rework or repave to provide an access aisle with surface slope not exceeding 2% in all directions.
ACS	*0080	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		Grade	COM SPC	Accessible Parking Spaces	Third accessible parking space (from left to right) has a non-compliant surface slope of up to 2.8%.	\$502.4	Rework or repave to provide an accessible parking space with surface slope not exceeding 2% in all directions.
ACS	*0088	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		Grade	COM SPC	Passenger Loading Zone by Main Entrance	Passenger loading zone has a non-compliant surface slope of up to 2.8%.	\$503.4	Restripe to provide a 60" (1524 mm) min. wide access aisle serving a 20 ft. (6096 mm) min. long vehicle pull up space with a surface slope not exceeding 2% in all directions (2010 ADA Fig. 503.3).
ACS	*0104	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Accessible Route From Main Entrance Leading to Public Rights-of-Way	Accessible route has a non-compliant running slope of up to 7.2 % that extends 45 ft (13.7 mt).	\$403.3	provide handrails on both sides of ramp and mount between 34" and 38" (863 mm - 965 mm) above the ramp surface to top of gripping surfaces, extending 12" (304 mm) min. beyond the top and bottom of the ramp segment or rework or repave accessible route to provide a cross slope not exceeding 5%.
ACS	0001	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0001	1st	COM SPC	Reception Counter	Reception counter is mounted at 43.75" (1111 mm) above the finished floor.	\$904.4.1	Provide an alternative counter or rework reception counter to provide a portion that is 36" (914 mm) min. long, mounted at 36" (914 mm) max. above the finished floor to the top (For a parallel approach to counter).
ACS	0004	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0004	1st	COM SPC	Quiet Room	Bed encroaches over sink and paper towel dispenser clear floor space.	\$305.3	Relocate bed to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0005	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Quiet Room	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 56.25" (1429 mm) above the finished floor to the highest operable part.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.3.1).
ACS	0006	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Quiet Room	Wall cabinets over the work surface are mounted at 65" (1651 mm) above the finished floor to the bottom shelf.	\$804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0007	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Quiet Room	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 60.5" (1537 mm) above the finished floor to the highest operable part.	\$308.2.1	Lower or install thermostat at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0008	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Unisex Accessible Restroom by Waiting Area	Water closet side wall grab bar is mounted at 37.25" (946 mm) above the finished floor to the top of the gripping surface.	\$604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. from rear wall to centerline of outer flange and mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.1)
ACS	0009	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Unisex Accessible Restroom by Waiting Area	Water closet rear wall grab bar is mounted at 37" (940 mm) above the finished floor to the top of the gripping surface.	\$604.5.2	Relocate rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface.
ACS	0010	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Unisex Accessible Restroom by Waiting Area	Paper towel dispenser protrudes into walkway, projecting more than 4" (102 mm) from back wall.	\$307.2	Relocate or recess paper towel dispenser so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0012	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Furniture encroaches into the maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate furniture to provide the required 24" (609 mm) min. maneuvering clearance on the pull side of the door for a parallel latch side approach and 54" (1370 mm) min. deep clear floor area (For door with a closer) (2010 ADA Fig. 404.2.4.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0013	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 54" (1372 mm) above the finished floor to paper.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to paper for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0014	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Urinal is mounted at 17.75" (451 mm) above the finished floor to top of rim.	\$605.2	Lower urinal and mount at 17" (431 mm) max. above the finished floor to top of rim. (2010 ADA Fig. 605.2)
ACS	0015	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Stall door swings into hand dryer clear floor space.	\$604	Relocate hand dryer to provide a 30" by 48" (762 mm by 1219 mm) min. unobstructed clear floor space (2010 ADA Fig. 305).
ACS	0016	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Toilet compartment (stall) door does not provide pull handles on both sides of the door near the latch.	\$604.8.1.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0017	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 51.75" (1314 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object (For toilet and bathing rooms only).
ACS	0018	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Water closet is centered at 19.25" (489 mm) from side wall.	\$604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0019	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Water closet side wall grab bar is mounted at 36.75" (933 mm) above the finished floor to the top of the gripping surface.	\$604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. from rear wall to centerline of outer flange and mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.1)
ACS	0020	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Men's Accessible Restroom on Left Side of Main Entrance	Water closet rear wall grab bar is mounted at 36.5" (927 mm) above the finished floor to the top of the gripping surface.	\$604.5.2	Relocate rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface.
ACS	0022	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0007	1st	COM SPC	Sewing Room	Telephone is mounted at 54.25" (1378 mm) above the finished floor to the highest operable part.	\$308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0023	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0008	1st	COM SPC	Women's Accessible Restroom on Left Side of Main Entrance	Permanent room identifying signage is mounted on the hinge side of the door.	\$703.4.1	Provide signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. from the baseline of the highest tactile character (2010 ADA Fig. 703.4.1).
ACS	0024	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Women's Accessible Restroom on Left Side of Main Entrance	Couch encroaches over maneuvering clearance on pull side of door for a parallel latch approach.	\$404.2.4	Remove couch to provide the required 24" (609 mm) min. maneuvering clearance on the pull side of the door for a parallel latch side approach and 54" (1370 mm) min. deep clear floor area (For door with a closer) (2010 ADA Fig. 404.2.4.1).
ACS	0025	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Women's Accessible Restroom on Left Side of Main Entrance	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 49" (1245 mm) above the finished floor to the highest operable part.	\$308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to the highest operable part for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0026	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Women's Accessible Restroom on Left Side of Main Entrance	Stall door swings into hand dryer clear floor space.	\$606.2	Relocate hand dryer to provide a 30" by 48" (762 mm by 1219 mm) min. unobstructed clear floor space (2010 ADA Fig. 305).
ACS	0027	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Women's Accessible Restroom on Left Side of Main Entrance	Toilet compartment (stall) door does not provide pull handles on both sides of the door near the latch.	\$604.8.1.2	Provided pull handles on both sides of the door near the latch and center door opening hardware between 34" and 48" (863 mm - 1219 mm) above the finished floor.
ACS	0028	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Women's Accessible Restroom on Left Side of Main Entrance	Coat hook is mounted beyond required reach allowed for approach provided and is mounted at 52.5" (1334 mm) above the finished floor.	\$603.4	Lower or install coat hook at 48" (1219 mm) max. above the finished floor for forward approach to object.
ACS	0029	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Women's Accessible Restroom on Left Side of Main Entrance	Water closet side wall grab bar is mounted at 37" (940 mm) above the finished floor to the top of the gripping surface.	\$604.5.1	Install a 42" (1066 mm) min. long side wall grab bar at 54" (1371 mm) min. from rear wall to centerline of outer flange and mount at 33"- 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface (2010 ADA Fig. 604.5.1)
ACS	0030	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Women's Accessible Restroom on Left Side of Main Entrance	Water closet rear wall grab bar is mounted at 36.25" (921 mm) above the finished floor to the top of the gripping surface.	\$604.5.2	Relocate rear wall grab bar and mount between 33" and 36" (838 mm - 914 mm) above the finished floor to the top of the gripping surface. Per 36.304(d)(2)(j) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0031	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Women's Accessible Restroom on Left Side of Main Entrance	Water closet is centered at 19.75" (502 mm) from side wall.	\$604.2	Relocate water closet and center between 16" and 18" (406 mm - 457 mm) from side wall (2010 ADA Fig. 604.2).
ACS	0033	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0010	1st	COM SPC	Ceramics Room No. 113	Bottom counter surface is mounted at 34.25" (870 mm) above the finished floor.	\$902.3	Rework to provide the top of the counter surface mounted between 28" (710 mm) min. and 34" (865 mm) max. above the finished floor or ground. For a facility that pre-dates the enactment of the ADA this dimension should be considered acceptable per 1990 ADA section 3.2 Dimensional Tolerances and 2010 ADA section 104.1 Construction and Manufacturing Tolerance.

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0034	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Ceramics Room No. 113	Bottom counter has a non-compliant 26" (660 mm) knee clearance.	§902.2	Provide counter with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance that is 30" (762 mm) min. wide and has a 17" (430 mm) horizontal projection.
ACS	0035	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Ceramics Room No. 113	Wall cabinets over the work surface are mounted at 54.25" (1378 mm) above the finished floor to the bottom shelf.	§804.5	Relocate wall cabinets, above the work surface, and mount at 48" (1219 mm) max. above the finished floor to the bottom shelf. Handles shall be mounted as close to the bottom as possible.
ACS	0036	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Ceramics Room No. 113	Cabinet encroaches into kitchen sink clear floor space.	§804.3.1	Relocate cabinet to provide a 30" by 48" (762 mm by 1219 mm) min. clear floor space for a forward approach to the sink.
ACS	0037	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Ceramics Room No. 113	Cabinet encroaches over paper towel dispenser clear floor space.	§305.3	Relocate cabinet to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space at paper towel dispenser (2010 ADA Figs. 305.3-305.5).
ACS	0038	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Ceramics Room No. 113	Paper towel dispenser is mounted beyond required reach allowed for approach provided and is mounted at 56.75" (1441 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install paper towel dispenser at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.3.1).
ACS	0039	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Ceramics Room No. 113	Trash bin encroaches over maneuvering clearance on the pull side of the door.	§404.2.4	Relocate trash bin to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0040	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Ceramics Room No. 113	Trash bin encroaches over telephone clear floor space.	§305.3	Relocate trash bin to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0041	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Ceramics Room No. 113	Telephone is mounted at 54.5" (1384 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0043	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0012	1st	COM SPC	Kiln No. 114	Shelf is mounted at 51.75" (1314 mm) above the finished floor to highest shelf.	§308.2.1	Lower or install shelf at 48" (1219 mm) max. above the finished floor to highest shelf (2010 ADA Fig. 308.2.1). <i>Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.</i>
ACS	0044	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Kiln No. 114	Kiln clear floor space is 54.5" (1384 mm) wide and does not provide the required diameter wheelchair turnaround space inside room due to a shelf.	§304.3	Remove shelf to provide the required clear 60" (1524 mm) min. diameter wheelchair turnaround space (2010 ADA Fig. 304.3.2).
ACS	0045	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Kiln No. 114	Maneuvering clearance on the pull side of the door is 13.5" (343 mm).	§404.2.4	Remove shelf to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door beyond the latch side and 60" (1524 mm) min. deep clear floor leveled area with slopes not exceeding 1:48 (2010 ADA Fig. 404.2.4.1).
ACS	0046	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Kiln No. 114	Trash bin and fire extinguisher encroach into sign clear floor space.	§703.4.2	Relocate trash bin and fire extinguisher to provide a clear floor space of 18" (455 mm) min. by 18" (455 mm) min. centered on the tactile characters, is provided beyond the arc of the door swing, between the closed position and 45° open position (2010 ADA Fig. 703.4.2).
ACS	0048	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Class Room No. 115	Telephone protrudes into walkway, projecting 4" (102 mm) from back wall, and is mounted at 48" (1219 mm) above the finished floor to its bottom leading edge.	§307.2	Relocate or recess telephone so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0050	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Class Room No. 115	Shelf is mounted at 62.75" (1594 mm) above the finished floor to highest shelf.	§308.2.1	Lower or install shelf at 48" (1219 mm) max. above the finished floor to highest shelf (2010 ADA Fig. 308.2.1).
ACS	0051	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Class Room No. 115	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 62" (1575 mm) above the finished floor to the centerline of the highest operable part.	§308.2.1	Lower or install thermostat at 48" (1219 mm) max. above the finished floor to the centerline of the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0053	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Fitness Room No. 116	Exercise machines and equipment have a non-compliant clear floor space.	§1004.1	Relocate exercise machines and equipment to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space, positioned for transfer or use by an individual seated in a wheelchair (2010 ADA Fig. 305.3, 305.5).
ACS	0054	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Fitness Room No. 116	Accessible route leading to the exercise equipment is reduced to 26" (660 mm).	§403.5.1	Relocate exercise equipment to provide a 36" (914 mm) min. clear width continuously (2010 ADA Fig. 403.5.1).
ACS	0055	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Fitness Room No. 116	Trash bin encroaches over maneuvering clearance on the pull side of the door.	§404.2.4	Relocate trash bin to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0056	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Fitness Room No. 116	Trash bin encroaches over telephone clear floor space.	§305.3	Relocate trash bin to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0057	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Fitness Room No. 116	Telephone is mounted at 54.5" (1384 mm) above the finished floor to the highest operable part.	§308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1).
ACS	0058	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Fitness Room No. 116	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 62.5" (1588 mm) above the finished floor.	§308.2.1	Lower or install thermostat at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).

**Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14**

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0059	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Fitness Room No. 116	Shelf is mounted beyond required reach range for approach provided and is mounted at 66.75" (1695 mm) above the finished floor.	\$811.3	Lower or install accessible shelf at 48" (1219 mm) max. above the finished floor (2010 ADA Fig. 308.3.1).
ACS	0061	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Lounge Room No. 118	Table has a non-compliant 26.75" (679 mm) knee clearance.	\$902.2	Provide seating with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance, that is 30" (762 mm) min. wide and has a 17" (430 mm) horizontal projection.
ACS	0062	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Lounge Room No. 118	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 63.5" (1613 mm) above the finished floor.	\$308.2.1	Lower or install thermostat at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0064	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Billiards Room No. 117	Trash bin encroaches over maneuvering clearance on the pull side of the door.	\$404.2.4	Relocate trash bin to provide the required 18" (457 mm) min. maneuvering clearance on the pull side of the door (2010 ADA Fig. 404.2.4.1).
ACS	0065	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Billiards Room No. 117	Trash bin encroaches over telephone clear floor space.	\$305.3	Relocate trash bin to provide a 30" by 48" (762 mm by 1219 mm) min. wheelchair clear floor space (2010 ADA Figs. 305.3-305.5).
ACS	0066	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Billiards Room No. 117	Telephone is mounted at 54" (1372 mm) above the finished floor to the highest operable part.	\$308.2.1	Lower or install telephone at 48" (1219 mm) max. above the finished floor to the highest operable part (2010 ADA Fig. 308.2.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0067	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Billiards Room No. 117	Table has a non-compliant clear floor space due to pedestal base.	\$902.2	Provide seating with a corresponding 30" by 48" (762 mm by 1219 mm) clear floor space, 27" (685 mm) min. bottom knee clearance above the finished floor and a 17" (430 mm) horizontal projection.
ACS	0068	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Billiards Room No. 117	Shelf is mounted beyond required reach range for approach provided and is mounted at 63.5" (1613 mm) above the finished floor.	\$811.3	Lower or install accessible shelf at 48" (1219 mm) max. above the finished floor for forward or side approach to object 10" (254 mm) max. deep (2010 ADA Fig. 308.3.1).
ACS	0069	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Billiards Room No. 117	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 68.25" (1734 mm) above the finished floor to the centerline of the highest operable part.	\$308.2.1	Lower or install thermostat at 48" (1219 mm) max. above the finished floor to the highest operable part for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0070	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Billiards Room No. 117	Cue stick holder is mounted beyond required reach allowed for approach provided and is mounted at 71" (1803 mm) above the finished floor.	\$308.3	Lower or install cue stick holder at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.3.1).
ACS	0071	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0015	1st	COM SPC	Corridor by Fitness Room No. 116	Flood light protrudes into walkway, projecting 5.75" (146 mm) from back wall, and is mounted at 74.5" (1892 mm) above the finished floor to its bottom leading edge.	\$307.2	Relocate or recess flood light so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0072	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0016	1st	COM SPC	Corridor by Sewing Room No. 112	Flood light protrudes into walkway, projecting 5.75" (146 mm) from back wall, and is mounted at 75.5" (1918 mm) above the finished floor to its bottom leading edge.	\$307.2	Relocate or recess flood light so that it does not project more than 4" (101 mm) from back wall to outer leading edge (2010 ADA Fig. 307.2).
ACS	0073	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Corridor by Sewing Room No. 112	Thermostat is mounted beyond required reach allowed for approach provided and is mounted at 67.75" (1721 mm) above the finished floor to the centerline of the highest operable part.	\$308.2.1	Lower or install thermostat at 48" (1219 mm) max. above the finished floor for forward approach to object (2010 ADA Fig. 308.2.1).
ACS	0003	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0003	1st	COM SPC	Quiet Room	Permanent room identifying signage is mounted at 61.25" (1556 mm) to the baseline of the highest tactile character.	\$703.4.1	We recommend providing signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0021	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0006	1st	COM SPC	Sewing Room No. 112	Permanent room identifying signage is mounted at 61.25" (1556 mm) to the baseline of the highest tactile character.	\$703.4.1	We recommend providing signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.

Fulton County ADA Transition Plan
SENIOR SERVICES
Appendix 7-14

RSC	Item No.	Department	Bldg Name	Address	Line	Fl.	Area Type: COM SPC/ PRGM	Room No. Name	Physical Obstacle	ADA Code	Proposed Correction
ACS	0032	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0009	1st	COM SPC	Ceramics Room No. 113	Permanent room identifying signage is mounted at 61.25" (1556 mm) to the baseline of the highest tactile character.	\$703.4.1	We recommend providing signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0042	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0011	1st	COM SPC	Kiln No. 114	Permanent room identifying signage is mounted at 60.75" (1543 mm) to the baseline of the highest tactile character.	\$703.4.1	We recommend providing signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0047	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0013	1st	COM SPC	Class Room No. 115	Permanent room identifying signage is mounted at 61.25" (1556 mm) to the baseline of the highest tactile character.	\$703.4.1	We recommend providing signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0052	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0014	1st	COM SPC	Fitness Room No. 116	Permanent room identifying signage is mounted at 61.25" (1556 mm) to the baseline of the highest tactile character.	\$703.4.1	We recommend providing signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0060	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Lounge Room No. 118	Permanent room identifying signage is mounted at 60.75" (1543 mm) to the baseline of the highest tactile character.	\$703.4.1	We recommend providing signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0063	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315		1st	COM SPC	Billiards Room No. 117	Permanent room identifying signage is mounted at 61" (1549 mm) to the baseline of the highest tactile character.	\$703.4.1	We recommend providing signage on latch side with raised characters and grade 2 Braille, mounted at 48 inches min. measured from the baseline of the lowest tactile character and 60 inches max. to the baseline of the highest tactile character (2010 ADA Fig. 703.4.1). Per 36.304(d)(2)(i) Safe harbor. Elements that comply with the corresponding technical requirements and scoping requirements for those elements in the 1991 Standards do not need to be modified in order to comply with the requirements set forth in the 2010 Standards.
ACS	0074	Senior Services	Southeast Neighborhood Senior Center	1650 New Town Circle SE Atlanta, GA 30315	0017	1st	COM SPC	Cafeteria	There was a meeting at the cafeteria therefore it was not surveyed.	\$216.6	There was a meeting at the cafeteria therefore it was not surveyed.